

SMS Incident Report


23/09/2021 11:13:54

Summary

CAD Number F3324064 **Status** Closed
Station Ilam Station
Incident Started 21/09/2021 12:23:16 **Incident Ended** 21/09/2021 13:52:13
Incident Type 1101: Structure fire with damage
Common Name
Address [REDACTED]
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 342627
Map Grid E [REDACTED] **Map Grid N** [REDACTED]
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 21/09/2021 14:45:47
Report Completed 15:4, Tue 21 Sep 2021 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
ILAM261	P1	12:24:02 21 Sep 2021	12:25:20 21 Sep 2021	12:28:02 21 Sep 2021	13:52:17 21 Sep 2021
SPRE221	P1	12:24:06 21 Sep 2021	12:24:53 21 Sep 2021	12:32:06 21 Sep 2021	13:12:41 21 Sep 2021



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
ILAM261	00:00:46	00:04:00	00:04:46	01:29:01
SPRE221	00:00:50	00:08:00	00:08:50	00:49:25

Message Log

Time	Message
12:23:52	https://web.pcl.govt.nz/?ecr [REDACTED]
12:23:52	INC INFO: HOUSE FIRE
12:23:54	** LOI search completed at 21/09/21 12:23:53
12:23:57	** Recommended unit ILAM261 for requirement PUMP (>1.0 km) ** Recommended unit
12:23:57	SPRE221 for requirement PUMP (>3.8 km)
12:23:59	PA Selcal used to Initiate Alerting. (ILAM261 at 3426 ILAM 193261)
12:23:59	PA Selcal used to Initiate Alerting. (SPRE221 at 3422 SPREYDON 192221)
12:24:03	ALERTING_COMPLETED ILAM261
12:24:04	FIRE IS IN KITCHEN
12:24:06	ALERTING_COMPLETED SPRE221
12:24:19	**
12:24:25	NO COLD/FLU SYMPTOMS
12:24:31	ALL PERSONS OUT
12:24:53	Unit SPRE221 [K1 : PROCEEDING TO INCIDENT]
12:25:20	Unit ILAM261 [K1 : PROCEEDING TO INCIDENT]
12:26:54	Unit ILAM261 [COMCEN COM : MESSAGE] FURTHER INFO PASSED (COPY)
12:28:03	Unit ILAM261 [K88 : PROPERTY FIRE APPARENTLY SMALL]
12:31:08	Unit ILAM261 [KC : UNIT CALLING]
12:31:43	Unit ILAM261 [SITREP :] SO [REDACTED] ONE KITCHEN FIRE 2 BA AND ONE HPD IN USE
12:32:06	Unit SPRE221 [K2 : IN ATTENDANCE AT INCIDENT]
12:50:37	Unit ILAM261 [KC : UNIT CALLING]
12:51:35	Unit ILAM261 [SITREP :] DAMPENING DOWN 4 BA, 2 HPD, TIC, PPV IN USE
13:11:12	Alarm Timer Extended: 0
13:12:26	Unit SPRE221 [KC : UNIT CALLING]
13:12:42	Unit SPRE221 [K10 : RE-COMMISSIONING APPLIANCE]
13:50:28	Unit ILAM261 [KC : UNIT CALLING]
13:52:13	Unit ILAM261 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM SITREP] SCENE LEFT WIT
13:52:13	H PROPERTY OWNER AND TENANT
13:52:17	Unit ILAM261 [K10 : RE-COMMISSIONING APPLIANCE]
14:45:46	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident

CAD Number F3324064

Incident Reporter [REDACTED]

Incident Controller

Distance Travelled (km)

Delay In Receiving Call

Property Details

Occupant [REDACTED]
 Building Owner Rented property
 General Property Use Flat, Apartment, Home unit
 Special Property Use Flats, Apartments, Units 3 to 10
 Purpose Group

Actions

Persons Reported Trapped
 Evacuation Status Fully evacuated
 Action Prior 1
 Action Prior 2
 Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	2

Origin

Location Kitchen, Cooking area
 Level Ground level

Equipment Used

Quantity	Equipment
2	Hose reel, high pressure delivery
1	Positive Pressure Ventilation Fan (PPV)
1	Gas Detector/PID
1	Equipment Not Listed

Equipment Involved

Equipment Involved

Year

Make

Model**Fire**

Arrival Condition	Small fire
Heat Source	Heat from electrical equipment: Properly operating
Termination Stage	
First Object Ignited	
First Object Material	
Second Object Ignited	
Second Object Material	
Indicated Cause	Heat source too close to combustibles
Certainty of Cause	High
Age of Person	Persons: 19 - 64 yrs
Ethnicity	██████████
Gender	██████
FAIP Service Offered	Unknown

Alarms

Type of Alarm	Domestic Smoke Alarms
Initiating Call	
Performance of System	Alerted occupants but detector not in room of origin
Failure/Ineffectiveness of system	
Number of sprinkler heads operated	

Released under the Official Information Act 1982