SMS Incident Report

22/05/2017 10:41:15

Summary

CAD Number F2310696 Status Closed

Station Grey Lynn Station

Incident Started 20/05/2017 17:03:47 Incident Ended 20/05/2017 18:34:15

Incident Type 1101: Structure fire with damage

Common Name

Address 42 JOHN STREET PONSONBY

Alarm Method 111 Telephone Alarm Level

PFA Number

Zone 142623

Map Grid E 1754967 Map Grid N 5920589

First Caller


Incident Closed 20/05/2017 18:34:15

Report Completed 0:49, Sun 21 May 2017 by Mark Shaw

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
GREY261	P1	17:05:09 20 May 2017	17:06:36 20 May 2017	17:11:33 20 May 2017	18:21:49 20 May 2017
AUCK207	PR	17:05:07 20 May 2017	17:06:55 20 May 2017	17:12:06 20 May 2017	17:47:54 20 May 2017
PARN251	P1	17:05:12 20 May 2017	17:06:40 20 May 2017	17:14:10 20 May 2017	17:58:54 20 May 2017
AUCKOSU1	SV	17:21:50 20 May 2017	17:22:02 20 May 2017	17:43:20 20 May 2017	18:09:02 20 May 2017

First Caller Contact



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
GREY261	00:01:22	00:06:24	00:07:46	01:18:02
AUCK207	00:01:20	00:06:59	00:08:19	00:44:07
PARN251	00:01:25	00:08:58	00:10:23	00:55:07

SMS Incident Report F2310696 2/6 22/05/2017 10:41:15

	AUCKOSU1	00:18:03	00:21:30	00:39:33	01:05:15
ł					

Notifications

Date	Time	Party Notified	
20 May 2017	17:17:58	OSU AUCKLAND	
20 May 2017	17:26:12	VECTOR	A.
20 May 2017	17:26:56	VECTOR WILL CALL BACK WITH AN ETA	
20 May 2017	17:28:07	AVON607 REDIRECTED K25 GREY LYNN	
20 May 2017	17:41:07	ETA 30MINS	
20 May 2017	17:43:09	ETA VECTOR 30MINS	.:0

Message Log

Time	Message
17:04:52	INC INFO: HOUSE FIRE
17:04:54	** LOI search completed at 20/05/17 17:04:54
17:05:01	** Recommended unit GREY261 for requirement PUMP (>1.8 km)
17:05:01	** Recommended unit AUCK207 for requirement PUMP (>2.1 km)
17:05:01	** Recommended unit PARN251 for requirement PUMP (>4.1 km)
17:05:47	CALLER NEXT DOOR NEIGHBOUR, BLACK SMOKE COMING FROM KITCHEN AND HALLWAY
17:05:58	DOESNT THINK NEIGHBOURS ARE THERE
17:06:36	Unit GREY261 [K1 : PROCEEDING TO INCIDENT]
17:06:40	Unit PARN251 [K1 : PROCEEDING TO INCIDENT]
17:06:55	Unit AUCK207 [K1 : PROCEEDING TO INCIDENT]
17:08:18	Unit GREY261 [COMCEN COM : MESSAGE] FURTHER INFO PASSED
17:11:34	Unit GREY261 [K77 : NOTHING SHOWING]
17:11:39	Unit GREY261 [K77 : NOTHING SHOWING]
17:12:06	Unit AUCK207 [K2 : IN ATTENDANCE AT INCIDENT]
17:14:10	Unit PARN251 [K2 : IN ATTENDANCE AT INCIDENT]
17:16:08	Unit GREY261 [KC : UNIT CALLING]
17:16:35	Unit GREY261 [SITREP :] SO SHAW. SINGLE STOREY HOUSE FIRE. 1 HPD IN USE.
17:16:35	CARRYING OUT SEARCH AND RESCUE
17:20:17	Unit GREY261 [KC : UNIT CALLING]
17:20:51	Unit GREY261 [SITREP :] SSO MARTIN. 1 DOG REMOVED FROM PROPERTY. FIRE
17:20:51	SUPPRESSED. VENTILATION IN PROGRESS
17:22:03	Unit AUCKOSU1 [K1 : PROCEEDING TO INCIDENT]
17:25:08	COVERING UNIT AVON607 DISPATCHED TO STATION AUCKLAND
17:25:08	TERMINAL: D0710063
17:29:30	Unit GREY261 [KC : UNIT CALLING]
17:29:54	Unit GREY261 [SITREP :] 1 DOG RESCUED. VENTILATION.

Omo inclucia report	1 23 10030	3/0	22/03/2017 10.41.13
17:30:06	Unit GREY261 [CC	OMCEN COM : MESSAGE] AUCKOSU ARE K1 TO	YOUR LOCATION
17:33:23	Unit GREY261 [K	C : UNIT CALLING]	
17:33:57	Unit GREY261 [SI	ITREP :] TOC (1704 HRS)	
17:43:21	Unit AUCKOSU1 [K2 : IN ATTENDANCE AT INCIDENT]	
17:47:55	Unit AUCK207 [K	3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
17:58:55	Unit PARN251 [K	3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
18:09:04	Unit AUCKOSU1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	×
18:21:19	Unit GREY261 [K	C : UNIT CALLING]	~ C)
18:21:46	Unit GREY261 [S	TOP : MESSAGE] PREMISES LEFT WITH OWNERS	S
18:21:51	Unit GREY261 [K	4 : ON RT INSIDE NORMAL TURNOUT AREA]	
18:34:15	** Assigned Result	t Code: STRU, Detailed Event Type: 1100, Qualifier 1	: Q1,
18:34:15	Qualifier 2:		

Incident

CAD NumberF2310696Incident ReporterMark ShawIncident ControllerSO ShawDistance Travelled (km)3Delay In Receiving Call

Property Details

Occupant

Building Owner Owner occupied
General Property Use Single house
Special Property Use Single house

Purpose Group

Actions

Persons Reported Trapped No

Evacuation Status Not occupied at time of incident

Action Prior 1 No action taken by Civilian/Occupant/Passerby

Action Prior 2

Action Taken Extinguishment and ventilation

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0

Civilians Evacuated

Origin

Location Lounge, Common room, TV room, Sitting room, Music room

Level Ground level

Equipment Used

Equip	oment
Hose reel, high pressure delivery	
Salvage/ventilation: PPV, Fan	
Thermal Imaging Camera	X
Vehicle Radio (LMR)	
Handheld Radio (or Cellphone)	
	Hose reel, high pressure delivery Salvage/ventilation: PPV, Fan Thermal Imaging Camera Vehicle Radio (LMR)

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Small fire

Heat Source Heat from electrical equipment: Defective or

faulty

Termination Stage Flame

First Object Ignited Power transfer and electrical equipment - not

classified above

First Object Material Plastics - not classified above

Second Object Ignited Interior wall covering

Second Object Material Gypsum board, Gib board, Elephant board

Indicated Cause Other electrical failure

Certainty of Cause High

Age of Person Persons: 17 - 64 yrs

Ethnicity Unknown
Gender Female

FAIP Service Offered No FAIP Service Accepted No

Alarms

Type of Alarm Initiating Call Domestic Smoke Alarms

Performance of System Alerted neighbour/passerby - detector not in room of origin

Failure/Ineffectiveness of system

Number of sprinkler heads operated

Structure

Area of One Floor		100
Age of Building	1946 - 1969	
Structural Frame Type	Timber frame unprotected (normal housing)	
Number of Floors		1
Number of Basements		0
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)	
Material Generating Most Flame	PVC	
Material Generating Most Smoke	PVC	
Avenue of Flame Travel	Wall covering	
Avenue of Smoke Travel	Combination of any of: ceiling, wall, floor finish	
Extent of Flame Damage	Confined to part of room or area of origin	
Area of Flame Damage		3
Extent of Smoke Damage	Confined to structure of origin	
Area of Smoke Damage		100
Extent of Water Damage	No damage of this type	
Area of Water Damage	C1	0
Extent of Fire Control Damage	No damage of this type	
Area of Fire Control Damage		0

Comments

5/21/2017 12:49:15 AM

Reporter Comments

Plug in Dehumidifier failed and burned. Some flame damage to wall in immediate vicinity. A lot of black smoke produced and spread throughout house. Occupant unsure if dehumidifier was running.

Mark Shaw

zeleased under the Official Information Act