
SMS Incident Report

20/10/2017 12:21:04

Summary		*
CAD Number	F2398133	Status Closed
Station	Timaru Station	X
Incident Started	16/10/2017 14:34:25	Incident Ended 16/10/2017 17:46:10
Incident Type	1101: Structure fire with damage	· . O`
Common Name		
Address		^O
Alarm Method	111 Telephone	Alarm Level 1
PFA Number		Sec. 1
Zone	358001	
Map Grid E	1460474	Map Grid N 5081757
First Caller	NZ FIRE SERVICE DISTRICT 5 C.I.	First Caller Contact
Incident Closed	16/10/2017 17:46:10	σ
Report Completed	9:35, Tue 17 Oct 2017 by Craig Ng	

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
TIMA804	PM	14:37:02 16 Oct 2017	14:37:45 16 Oct 2017	14:41:04 16 Oct 2017	15:56:16 16 Oct 2017
WASH817	PR	14:37:04 16 Oct 2017	14:37:36 16 Oct 2017	14:43:49 16 Oct 2017	15:52:07 16 Oct 2017
FISTHCANT1	FSO	15:29:16 16 Oct 2017	15:29:25 16 Oct 2017	15:30:30 16 Oct 2017	16:04:47 16 Oct 2017



20/10/2017 12:21:04

Date	Time	Party Notified
16 Oct 2017	14:47:37	AREA SOUTH CANTERBURY PAGED RE
16 Oct 2017	14:49:44	AREA SOUTH CANTERBURY MARTYN BENNETT ACKD PAGE
16 Oct 2017	15:03:26	AREA SOUTH CANTERBURY PAGED RE
16 Oct 2017	15:07:07	AREA SOUTH CANTERBURY ACKD FURTHER UPDATE
16 Oct 2017	15:16:39	PAGED FI STH CANTERBURY BEVAN FINDLAY AND MURRAY CAIRNS
16 Oct 2017	15:19:18	RFOM SOUTH CANTERBURY (BEVAN FINDLAY) ACL - TRANSFERED TO TIMA804

Message Log

Notifications

Time	Message
14:36:44	INC INFO: CEILING FIRE
14:36:47	** LOI search completed at 16/10/17 14:36:47
14:36:55	** Recommended unit TIMA804 for requirement PUMP (>1.1 km)
14:36:55	** Recommended unit WASH817 for requirement PUMP (>3.7 km)
14:37:11	THIS IS SECOND HAND INFO. FROM TIMARU STATION
14:37:22	FIRE IS BELIEVED OUT
14:37:37	Unit WASH817 [K1 : PROCEEDING TO INCIDENT]
14:37:40	AL: PAGING ACK RECEIVED FROM STATION 3581 at 16/10/17 14:37:40
14:37:46	Unit TIMA804 [K1 : PROCEEDING TO INCIDENT]
14:37:53	AL: PAGING ACK RECEIVED FROM STATION 3580 at 16/10/17 14:37:53
14:39:13	Unit TIMA804 [COMCEN COM : MESSAGE] FURTHER INFO PASSED
14:41:02	*** 🧭
14:41:05	Unit TIMA804 [K77 : NOTHING SHOWING]
14:41:37	T3 INCORRECT ATTEMPTS TO INPUT ADDRESS
14:43:50	Unit WASH817 [K2 - IN ATTENDANCE AT INCIDENT]
14:44:49	Unit TIMA804 [KC ; UNIT CALLING]
14:45:28	Unit TIMA804 [SITREP :] SO NG, K11A
14:45:28	OWNERS
14:45:33	Unit TIMA804 [K11A : AMBULANCE REQUIRED]
14:45:35	
14:45:46	Unit TIMA804 [KC : UNIT CALLING]
14:45:49	FIR2AMB CAN WE HAVE YOUR ATTENDANCE FOR ONE PATIENT WITH
14:46:12	Unit TIMA804 [SITREP :] FIRE IN KITCHEN EXTRACTOR SYSTEM OOA
14:46:20	AMBO EVENT 0277-3-2017/10/16-FIR LINKED AT 16/10/2017 14:46:20
14:59:35	Unit TIMA804 [KP : PRIORITY MESSAGE]
15:00:14	Unit TIMA804 [KP : PRIORITY MESSAGE] AMB HAS
15:00:14	

IS Incident Report	F2398133 3/6 2	0/10/2017 12:21:
15:00:24	Unit TIMA804 [K11A : AMBULANCE REQUIRED]	
15:00:48	FIR2AMB AMB REQUIRED URGENTLY PERSON WITH	
15:00:48		
15:03:37	Unit TIMA804 [COMCEN COM : MESSAGE] ETA FOR AMBO PASSED	\mathbf{r}
15:06:06	Unit TIMA804 [KC : UNIT CALLING]	
15:06:57	Unit TIMA804 [SITREP :]	
15:12:57	Unit TIMA804 [KC : UNIT CALLING]	
15:14:18	Unit TIMA804 [K11F : FIRE SAFETY REQUIRED]	
15:14:57	INC INFO: CEILING FIRE TOC 1436 TOA 1441	
15:16:40	Unit WASH817 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]	
15:18:40	**	
15:29:25	Unit FISTHCANT1 [K1 : PROCEEDING TO INCIDENT]	
15:30:31	Unit FISTHCANT1 [K2 : IN ATTENDANCE AT INCIDENT	
15:52:08	Unit WASH817 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
15:55:32	Unit TIMA804 [KC : UNIT CALLING]	
15:55:59	Unit TIMA804 [STOP : MESSAGE] SCENE LEFT WITH FIRE SAFETY	
15:56:17	Unit TIMA804 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
16:04:48	Unit FISTHCANT1 [K6 : ON TELEPAGER]	
17:46:09	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,	
17:46:09	Qualifier 2:	
ncident		
CAD Number	F2398133	
ncident Reporter	Craig Ng	
ncident Keporter		
-	SO Ng	
ncident Controller	SO Ng	
ncident Controller Distance Travelled (kr	SO Ng 4	
ncident Controller Distance Travelled (kr	SO Ng 4	
ncident Controller Distance Travelled (kr Delay In Receiving Ca	SO Ng 4	
ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details	SO Ng 4	
ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details Dccupant	so Ng m) 4 all	
ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details Dccupant Building Owner	m) 4 all Rented property	
ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details Dccupant Building Owner General Property Use	SO Ng m) 4 all Rented property Single house	
ncident Reporter ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details Occupant Building Owner General Property Use Special Property Use Purpose Group	SO Ng m) 4 all Rented property Single house	
ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details Dccupant Building Owner General Property Use Special Property Use	SO Ng m) 4 all Rented property Single house	
ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details Dccupant Building Owner General Property Use Special Property Use Purpose Group	SO Ng m) 4 all Rented property Single house	
ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details Dccupant Building Owner General Property Use Special Property Use	so Ng m) 4 Rented property Single house Single house	
ncident Controller Distance Travelled (kr Delay In Receiving Ca Property Details Dccupant Building Owner General Property Use Special Property Use Purpose Group	so Ng m) 4 Rented property Single house Single house	

SMS Incident Report	F2398133	4/6	20/10/2017 12:21:04
Action Prior 2	No action take	en by Civilian/Occupant/Passerby	
Action Taken	Extinguishme	nt and ventilation	
			$\mathbf{\circ}$

Civilians

Civilians		
Civilians Rescued	⁵	0
Civilians Extricated		0
Civilians Assisted		2
Civilians Evacuated		
	V V	
Origin		
-		

Location	Kitchen, Cooking area	•.0	
Level	Ground level		

Equipment Used

Quantity	Equipment
0	Bucket pump or buckets of water - by Occupant/Passerby
1	First aid kit, including O2 units, surgical gloves
1	Ladder
1	Thermal Imaging Camera
1	Salvage/ventilation: PPV, Fan

Equipment Involved

• •	
Equipment Involved	0
Year	
Make	Turbo
Model	unsure
Fire	
Arrival Condition	Out on arrival
Heat Source	Heat from electrical equipment: Defective or faulty
Termination Stage	Overheat
First Object Ignited	Electronic componentry
First Object Material	Plastics - not classified above
Second Object Ignited	Interior wall covering
Second Object Material	Gypsum board, Gib board, Elephant board
Indicated Cause	Other electrical failure
Certainty of Cause	Medium
Age of Person	Persons: 17 - 64 yrs
Ethnicity	Asian / Indian

MS Incident Report F2398		5/6	20/10/2017 12:21:0
Gender	Female		
FAIP Service Offered	No	FAIP Service Accepted	No
Alarms			ço.
Type of Alarm Initiating Call	Domestic Smok	e Alarms	5
Performance of System	Detector not in r	room of origin - not classified above	
Failure/Ineffectiveness of system	Detector not in r	room of origin	
Number of sprinkler heads operated		Y C	
Structure			
Area of One Floor			1
Age of Building		1946 - 1969	
Structural Frame Type		Brick, Blocks etc	
Number of Floors			
Number of Basements			
Internal Wall Lining		Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining		Fibrous plaster	
Material Generating Most Fl	ame	Plastics - not classified above	
Material Generating Most Si	moke	Plastics - not classified above	
Avenue of Flame Travel		Unknown	
Avenue of Smoke Travel		No travel	
Extent of Flame Damage		Confined to room of origin	
Area of Flame Damage		(7)	
Extent of Smoke Damage		Confined to room of origin	
Area of Smoke Damage			
Extent of Water Damage		No damage of this type	
Area of Water Damage			
Extent of Fire Control Dama	ige	No damage of this type	
Area of Fire Control Damag	• 5		
Casualties			
asualty Number 1	S		
Gender	75	Female	
Age			
Apparent Injury			
Ethnicity		Asian / Indian	
Severity of Injury			

MS Incident Report F2398133	6/6	20/10/2017 12:21:0
Bleeding	No	
Action by Fire Flghters	Provided basic first aid	
Condition Before Injury	Awake, unimpaired	\mathbf{O}
How Removed	Taken to hospital: Ambulance	e e e e e e e e e e e e e e e e e e e
_ocation at Ignition	Person in room or space of fire origin	0
Factor Preventing Escape	NOTHING preventing escape	
Activity When Injured	Fire control attempt	×
Cause of Injury	Exposed to fire products	G
/ictim Aware of Fire	Victim alerted by other than domestic smoke	
Room Where Victim Found	Unable to classify	
ocation Where Victim Found	Unable to classify	
amiliarity With Property	Unknown	
On brigade arrival, turned the rangehood on and heard	10/17/2017 9:33:30 AM were still inside house. was cooking. She a bang, then the rangehood caught fire. She put it	Reporter Comments
front face and that was all. Concerns about raising alarm and n	bod I am not 100%. It had the word Turbo on the	
patient to outside for 1st aid.		
Harcourts property manager receive	ed initial phone call from the second .	
Fire Safety Craig Chambers attende	ed.	
	0	
	8	Craig Ng
	2	0
4	S	
~		
7)		
S		
The second se		
05		