

Site Location: Waikowhai Boardwalk (stage 1) / Bamfield Reserve & Accessway

Overall Description: Two sections of the timber constructed coastal boardwalk have been seriously damaged by cliff edge landslips bringing down trees & soil onto the boardwalk platform - damaging the timber decking, rails, underbearers and possibly structural posts, and at the western end of the boardwalk there is a landslip that has brought down bush & soil onto the concrete pathway damaging the bush track pathway & steel fencing, this pathway leads through the Bamfield Reserve to the local roadway entries.

Location 1 & 2

2 landslips onto the Waikowhai Boardwalk (stage 1) Bamfield Reserve

<i>SAP ID</i>	<i>Asset Type</i>	<i>Length of damaged section</i>	<i>Total length of asset</i>	<i>Install Date</i>
1000185011	Boardwalk structure	5-10m (estimate only)	400m (estimate only – not recorded)	Not sure, (not recorded - good condition)
1000185011	Boardwalk structure	5-10m (estimate only)	400m (estimate only – not recorded)	Not sure, (not recorded - good condition)

Location 3

1 landslip onto the concrete bush track pathway, Bamfield Reserve & Accessway

<i>SAP ID</i>	<i>Asset Type</i>	<i>Length of damaged section</i>	<i>Total length of asset</i>	<i>Install Date</i>
1000159602	Footpath Ry477	5-10m (estimate only)	150m (estimate only – not recorded)	Not sure, (not recorded - good condition)
	Metal Fence	5-10m (estimate only)	50m (estimate only – not recorded)	Not sure, (not recorded - good condition)

Details

<i>1. Which event each asset was damaged</i>	<i>Slips occurred in the Anniversary weekend storm 27 Jan 2023</i>
<i>2. How large is the site/park and length of asset</i>	<i>As above estimates Bamfield Reserve – 1,923M2 SAP ID FLOC 21630-L100</i>
<i>3. How old is asset</i>	<i>Not sure</i>

4. What is the main asset in the insurance schedule for the park/reserve and how far is this from the damaged auxiliary asset?	No main asset for this Bamfield reserve. damages to the timber boardwalk structure, and concrete pathway & metal fencing in the reserve.
5. Main asset ID number in the Insurance Schedule	
6. Sum Insured.	
7. AC advice/extent of cover in the Insurance Schedule	
8. By whom and when was damage to asset reported.	Feb 2023 Reported by AC Staff, landslips onto the boardwalk structure & reserve pathway, and slips reported located behind houses along this coastline cliff edge of Bamfield reserve
8. Who provided the initial reinstatement value	

Aerial of damage



2 x landslips onto the Waikowhai timber boardwalk – approximate location shown in red on R/H side of above area snapshot,

1 x landslip onto the bush track concrete pathway – approximate location shown in red on L/H side of area snapshot.

4 photos follow of the damaged timber boardwalk structure.



1.

2.





3.

4.

