SMS Incident Report

01/06/2021 11:37:33

Summary		5x
CAD Number	F3237517	Status Closed
Station	Henderson Station	
Incident Started	06/05/2021 20:17:22	Incident Ended 07/05/2021 01:48:00
Incident Type	1102: Structure fire with no damage	
Common Name	COUNTDOWN HENDERSON	
Address	Catherine Place Henderson	
Alarm Method	111 Telephone	Alarm Level 3
PFA Number		<u>k</u> O.
Zone	146500	
Map Grid E	1745459	Map Grid N 5917144
First Caller	,	irst Caller Contact
Incident Closed	07/05/2021 15:10:11	
Report Completed	10:55, Wed 12 May 2021 by	
Responses		

Responses

Recipinede					
Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
HEND657	PR	20:18:38 06 May 2021	20:20:16 06 May 2021	20:21:03 06 May 2021	01:55:34 07 May 2021
HEND651	P1	20:18:26 06 May 2021	20:23:48 06 May 2021	20:25:33 06 May 2021	23:49:51 06 May 2021
TEAT664	РМ	20:18:40 06 May 2021	20:20:26 06 May 2021	20:25:52 06 May 2021	23:18:01 06 May 2021
AUCK2018	сини	20:20:18 06 May 2021	20:22:23 06 May 2021	20:36:24 06 May 2021	00:23:47 07 May 2021
GLEN641	P 1	20:29:33 06 May 2021	20:30:46 06 May 2021	20:37:06 06 May 2021	23:47:10 06 May 2021
WEST671	P1	20:33:49 06 May 2021	20:34:12 06 May 2021	20:41:19 06 May 2021	23:26:04 06 May 2021
TEAT662	P2	20:29:30 06 May 2021	20:37:01 06 May 2021	20:41:27 06 May 2021	23:29:28 06 May 2021
AUCK205	HPNP	20:29:27 06 May 2021	20:31:55 06 May 2021	20:43:51 06 May 2021	21:59:42 06 May 2021
WEST672	P2	20:33:49 06 May 2021	20:38:28 06 May 2021	20:45:14 06 May 2021	22:44:52 06 May 2021
AUCKOSU3	SV	20:31:52 06 May 2021	20:32:10 06 May 2021	20:46:56 06 May 2021	00:02:14 07 May 2021
AVON607	PR	20:34:02 06 May 2021	20:34:08 06 May 2021	20:47:54 06 May 2021	00:57:39 07 May 2021

SMS Incident Report F3237517

2/17

01/06/2021 11:37:33

AVON6015	BA	20:34:02 06 May 2021	20:36:45 06 May 2021	20:50:13 06 May 2021	01:06:43 07 May 2021
BALM611	P1	20:35:34 06 May 2021	20:36:18 06 May 2021	20:51:18 06 May 2021	00:59:02 07 May 2021
WAIA711	P1	20:33:48 06 May 2021	20:40:03 06 May 2021	20:51:46 06 May 2021	23:50:21 06 May 2021
BALM6117	ST	20:35:35 06 May 2021	20:37:57 06 May 2021	20:52:05 06 May 2021	00:48:24 07 May 2021
WAIT771	P1	20:37:59 06 May 2021	20:42:32 06 May 2021	20:52:31 06 May 2021	22:43:35 06 May 2021
ELLE274	PM	20:33:55 06 May 2021	20:36:28 06 May 2021	20:53:16 06 May 2021	23:02:35 06 May 2021
OTAH3112	HL	20:34:05 06 May 2021	20:36:21 06 May 2021	20:59:15 06 May 2021	22:51:18 06 May 2021
AUCKCITY4	OF	20:38:16 06 May 2021	20:43:12 06 May 2021	21:00:31 06 May 2021	00:09:53 07 May 2021
WAITEMATA1	OF	20:44:15 06 May 2021	20:48:04 06 May 2021	21:02:21 06 May 2021	22:30:33 06 May 2021
REGION1G	OF	20:29:33 06 May 2021	20:30:09 06 May 2021	21:08:52 06 May 2021	00:08:40 07 May 2021
PARN256	TL	20:33:58 06 May 2021	20:34:09 06 May 2021	21:09:27 06 May 2021	22:19:54 06 May 2021
FIWAITEM4	FSO	20:44:56 06 May 2021	20:45:00 06 May 2021	21:12:01 06 May 2021	12:42:28 07 May 2021
AUCKOSU2	SV	21:02:45 06 May 2021	21:02:47 06 May 2021	21:23:40 06 May 2021	23:41:38 06 May 2021
AUCKOSU4	CV	20:33:42 06 May 2021	21:04:24 06 May 2021	21:33:29 06 May 2021	23:57:24 06 May 2021
OTAH311	P1	20:34:05 06 May 2021	20:40:25 06 May 2021	21:43:59 06 May 2021	22:51:21 06 May 2021
VSOWAITEM3	VSO	20:52:24 06 May 2021	20:59:00 06 May 2021	21:46:37 06 May 2021	00:44:43 07 May 2021
TAKA8019	ОТ	20:52:25 06 May 2021	21:48:09 06 May 2021	21:48:10 06 May 2021	00:23:46 07 May 2021
FENORTH2	ОТ	09:21:55 07 May 2021	09:22:00 07 May 2021	09:44:43 07 May 2021	13:07:51 07 May 2021
FIWAITEM3	FSO	11:42:24 07 May 2021	11:43:34 07 May 2021	11:43:34 07 May 2021	13:03:38 07 May 2021
AIRAKL3633	MED				22:10:13 06 May 2021
AUCKOSU	O sv	20:29:08 06 May 2021			20:45:33 06 May 2021
Start->Alert	7 min	10 min			
0 min			15 min		30 min
	Alert Arriv	->1st al			

Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
HEND657	00:01:16	00:02:25	00:03:41	05:38:12
HEND651	00:01:04	00:07:07	00:08:11	03:32:29
TEAT664	00:01:18	00:07:12	00:08:30	03:00:39
AUCK2018	00:02:56	00:16:06	00:19:02	04:06:25
GLEN641	00:12:11	00:07:33	00:19:44	03:29:48
WEST671	00:16:27	00:07:30	00:23:57	03:08:42
TEAT662	00:12:08	00:11:57	00:24:05	03:12:06
AUCK205	00:12:05	00:14:24	00:26:29	01:42:20
WEST672	00:16:27	00:11:25	00:27:52	02:27:30
AUCKOSU3	00:14:30	00:15:04	00:29:34	03:44:52
AVON607	00:16:40	00:13:52	00:30:32	04:40:17
AVON6015	00:16:40	00:16:11	00:32:51	04:49:21
BALM611	00:18:12	00:15:44	00:33:56	04:41:40
WAIA711	00:16:26	00:17:58	00:34:24	03:32:59
BALM6117	00:18:13	00:16:30	00:34:43	04:31:02
WAIT771	00:20:37	00:14:32	00:35:09	02:26:13
ELLE274	00:16:33	00:19:21	00:35:54	02:45:13
OTAH3112	00:16:43	00:25:10	00:41:53	02:33:56
AUCKCITY4	00:20:54	00:22:15	00:43:09	03:52:31
WAITEMATA1	00:26:53	00:18:06	00:44:59	02:13:11
REGION1G	00:12:11	00:39:19	00:51:30	03:51:18
PARN256	00:16:36	00:35:29	00:52:05	02:02:32
FIWAITEM4	00:27:34	00:27:05	00:54:39	16:25:06
AUCKOSU2	00:45:23	00:20:55	01:06:18	03:24:16
AUCKOSU4	00:16:20	00:59:47	01:16:07	03:40:02
OTAH311	00:16:43	01:09:54	01:26:37	02:33:59
VSOWAITEM3	00:35:02	00:54:13	01:29:15	04:27:21
TAKA8019	00:35:03	00:55:45	01:30:48	04:06:24
FENORTH2	13:04:33	00:22:48	13:27:21	16:50:29
FIWAITEM3	15:25:02	00:01:10	15:26:12	16:46:16
AIRAKL3633				01:52:51
AUCKOSU	00:11:46			00:28:11
AUCRUSU	00.11.40			00.20.11

Notifications

Date	Time	Party Notified
06 May 2021	20:21:54	AAC WAITEMATA
06 May 2021	20:23:33	HEND657 ADHOC BELLS FAILED

06 May 2021	20:29:16	AMBULANCE VIA INTERCAD
06 May 2021	20:29:16	POLICE VIA INTERCAD
06 May 2021	20:29:32	VECTOR RE 2ND ALARM
06 May 2021	20:30:36	VSO WAITEMATA 3 PAGED
06 May 2021	20:32:20	VSO WAITEMATA 3 PAGE ACK
06 May 2021	20:32:54	POWER RE 3RD ALARM
06 May 2021	20:33:04	AAC RE 2ND
06 May 2021	20:33:11	AAC WAITEMATA RE 2ND
06 May 2021	20:33:17	AC RE 2ND
06 May 2021	20:35:14	HENDERSON POLICE
06 May 2021	20:35:33	AMB VIA PHONE - TO RESPOND
06 May 2021	20:36:14	POLICE HENDERSON RINGS IN THEY HAVE AN INCIDENT IN TE ATATU SO NOT AVAILABLE
06 May 2021	20:36:49	VSO WAITEMATA PAGED 3RD ALARM
06 May 2021	20:37:01	FI WAITEMATA4 PAGED 3RD ALARM
06 May 2021	20:38:42	REGION1A PAGE ACK
06 May 2021	20:40:52	VECTOR ETA 10 MINS
06 May 2021	20:42:12	WAITEMATA 1C ACK PAGE - DETAILS PASSED (ON HOLD AWAITING SITREP)
06 May 2021	20:45:17	FI WAITE4 ACK PAGE - RESPONDING
06 May 2021	20:53:51	VSOWAITEM3 RESPONDING W TAKA8019 UNIFORM TRAILER
06 May 2021	20:59:13	AUCK2018 (ICU-1) VIA PHONE RINGS TO VM
06 May 2021	20:59:34	AUCK2018 (ICU-2) VIA PHONE RINGS TO VM
06 May 2021	20:59:52	AUCK2018 (ICU-GSM) VIA PHONE RINGS TO VM
06 May 2021	21:00:22	HEND657 SMARTPHONE - NO ANSWER
06 May 2021	21:04:40	TITIRANGI FIRE - TITI692 MANNED ON STATION
06 May 2021	22:58:23	TITI692 NOW UNMANNED
06 May 2021	23:19:32	JTOC POHONE IN TO ASK IF WE STILL REQUIRE GREAT NORTH RD CLOSED OFF
06 May 2021	23:26:34	JTOC PER PHONE TO OPEN GNR
07 May 2021	00:03:41	JTOC - ALL ROADS AROUND FIRE GROUND HAVE NOW RE OPENED
07 May 2021	00:47:35	REGION 1G RE 3RD ALARM @ 2036HRS
07 May 2021	00:47:49	WAITEMATE AREA 3RD ALARM @ 2036HRS
07 May 2021	00:48:09	AC WAITEMATA RE 3RD ALARM @ 2036HRS
07 May 2021	00:48:27	AAC WAITEMATA RE 3RD ALARM @2036HRS
07 May 2021	00:48:50	AAC RE 3RD ALARM @ 2036HRS
07 May 2021	01:29:51	POLICE VIA INTERCAD
07 May 2021	01:29:52	- APPEARED TO BE LOOKING AROUND, VERY 1C
07 May 2021	07:05:26	VIA PHONE FROM NICK LINTON, PLEASE RE-ATTACH ME TO THIS EVENT, I AM GOING OU
07 May 2021	09:21:43	VIA PHONE FROM WHO IS A FIRE ENGINEER WILL BE ATTENDING, GOING K1 NO

SMS Incident Report	t F32375 [,]	7 5/17	01/06/2021 11:37:33
07 May 2021	11:30:20	FIWAITEM4 (NICK LINTON) PAGED - WELFARE CHECK AND FENORTH2	FOR WAITEM4

Message Log

Time	Message
20:17:58	https://web.pcl.govt.nz/?ecn=
20:17:58	INC INFO: FIRE IN AISLE IN COUNTDOWN
20:17:59	** LOI search completed at 06/05/21 20:17:59
20:18:10	** Recommended unit HEND657 for requirement PUMP (>0.4 km) ** Recommended unit
20:18:10	HEND651 for requirement PUMP (>0.4 km) ** Recommended unit TEAT664 for requirem
20:18:10	ent CANBACKUP (>2.8 km)
20:18:12	PA Selcal used to Initiate Alerting. (HEND657 at 1465 HENDERSON 182651)
20:18:12	Station Selcal used to Initiate Alerting. (HEND651 at 1465 HENDERSON 182652)
20:18:12	PA Selcal used to Initiate Alerting. (TEAT664 at 1466 TE ATATU 182661)
20:18:21	INFRONT OF GROCERIES
20:18:24	Unit HEND651 failed to contact via Selcal
20:18:26	ALERTING_COMPLETED HEND651
20:18:28	EVACUATION TAKEN PLACE
20:18:36	Unit HEND657 failed to contact via Selcal
20:18:38	ALERTING_COMPLETED HEND657
20:18:40	ALERTING_COMPLETED TEAT664
20:18:59	ADVISED CALLER TO ACTIVATE THEMANUAL CALLPOINT TO EVAC THE BUILDING
20:19:10	FIRE IN THE FRIDGE NEXT TO THE COOLER AISLE
20:19:15	PEOPLE ARE EVACUATING
20:19:18	** PFA/CPN search completed
20:19:40	FRIDGE NEXT TO THE FRONT CHECKOUTS
20:19:48	FIRE GETTING BIGGER
20:19:55	
20:20:11	** Requirement COMU added for alarm level 1
20:20:13	** Recommended unit AUCK2018 for requirement COMU (>11.6 km)
20:20:15	PA Selcal used to Initiate Alerting. (AUCK2018 at 1420 AUCKLAND CITY 182201)
20:20:16	Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
20:20:18	ALERTING_COMPLETED AUCK2018
20:20:20	ALARM HAS ONLY JUST ACTIVATED - EVAC NOT TAKEN PLACE AS YET
20:20:26	Unit TEAT664 [K1 : PROCEEDING TO INCIDENT]
20:20:48	** PFA/CPN search completed
20:21:03	Unit HEND657 [K77 : NOTHING SHOWING]
20:21:38	AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 05-06-21 20:21:38

20:22:02	** Cross Referenced to Event # F3237518 at: 06/05/21 20:22:02
20:22:03	** Cross Referenced to Event # F3237519 at: 06/05/21 20:22:03
20:22:23	Unit AUCK2018 [K1 : PROCEEDING TO INCIDENT]
20:22:30	Unit HEND657 [KC : UNIT CALLING]
20:22:45	DISP NOTE HYDRANTS NOT PASSED FOR MULTIPLE CALLS DUE TO HAVING TO CHECK FOR IGC
20:22:45	REQUIREMENT AND DISPATCH COMMAND UNIT & TEAT664 FILLS REQUIREMENT FOR AERIAL RES
20:22:45	PONSE
20:23:15	Unit HEND657 [SITREP :] SSO PS SMOKE SPRINKLER ACTIVATED AREA U, Z
20:23:48	Unit HEND651 [K1 : PROCEEDING TO INCIDENT]
20:25:33	Unit HEND651 [K2 : IN ATTENDANCE AT INCIDENT]
20:25:41	Unit HEND651 [K2 : IN ATTENDANCE AT INCIDENT]
20:25:52	Unit TEAT664 [K2 : IN ATTENDANCE AT INCIDENT]
20:25:56	Unit HEND651 [K2 : IN ATTENDANCE AT INCIDENT]
20:28:23	Unit HEND657 [KP : PRIORITY MESSAGE]
20:28:55	Unit HEND657 [KP : PRIORITY MESSAGE] STRU FIRE IN COUNTDOWN TX 2ND ALARM SPRINK
20:28:55	ER IS HOLDING AT PRESENT TIME
20:29:07	Pager used to Initiate Alerting.
20:29:07	Unit AUCKOSU failed to contact via Selcal
20:29:08	ALERTING_COMPLETED AUCKOSU
20:29:09	INC INFO: BUILDING FIRE - 2ND ALARM
20:29:15	FIR
20:29:16	AMBO EVENT 0837-1-2021/05/06-FIR LINKED AT 06/05/2021 20:29:16
20:29:16	2AMB
20:29:21	2ND ALARM FYLONLY
20:29:21	** Alarm level updated to 2
20:29:21	** Recommended unit AUCK205 for requirement AERIAL (>11.6 km) ** Recommended un
20:29:21	it TEAT662 for requirement PUMP (>2.8 km) ** Recommended unit GLEN641 for requi
20:29:21	rement PUMP (>3.6 km)
20:29:23	PA Selcal used to Initiate Alerting. (AUCK205 at 1420 AUCKLAND CITY 182201)
20:29:24	PA Selcal used to Initiate Alerting. (TEAT662 at 1466 TE ATATU 182662)
20:29:24	PA Selcal used to Initiate Alerting. (GLEN641 at 1464 GLEN EDEN 182641)
20:29:27	ALERTING_COMPLETED AUCK205
20:29:30	ALERTING_COMPLETED TEAT662
20:29:32	Pager used to Initiate Alerting.
20:29:33	ALERTING_COMPLETED REGION1G
20:29:33	ALERTING_COMPLETED GLEN641
20:29:33	ALERTING_COMPLETED REGION1G

20:29:34	FIR2POL: 2ND ALARM FYI
20:29:41	FIR2AMB: 2ND ALARM FYI
20:29:54	** PFA/CPN search completed
20:30:46	Unit GLEN641 [K1 : PROCEEDING TO INCIDENT]
20:31:49	Unit HEND651 [KP : PRIORITY MESSAGE]
20:31:52	Pager used to Initiate Alerting.
20:31:52	Unit AUCKOSU3 failed to contact via Selcal
20:31:52	ALERTING_COMPLETED AUCKOSU3
20:31:55	Unit AUCK205 [K1 : PROCEEDING TO INCIDENT]
20:32:10	Unit AUCKOSU3 [K1 : PROCEEDING TO INCIDENT]
20:32:17	Unit HEND651 [KP : PRIORITY MESSAGE] TX 3RD ALARM ENSURE ST IN ON RESPONSE
20:32:23	Unit AUCK205 [K1 : PROCEEDING TO INCIDENT]
20:32:27	INC INFO: BUILDING FIRE - 3RD ALARM
20:32:46	** Requirement PUMP added for alarm level 2
20:32:49	AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 05-06-21 20:32:49
20:33:23	** Alarm level updated to 3
20:33:23	** Recommended unit WEST671 for requirement CANBACKUP (>7.1 km) ** Recommended
20:33:23	unit WEST672 for requirement PUMP (>7.1 km) ** Recommended unit ELLE274 for req
20:33:23	uirement AERIAL (>15.5 km) ** Recommended unit PARN256 for requirement AERIAL (
20:33:23	>14.0 km) ** Recommended unit AVON6015 for requirement BAT (>6.4 km) ** Recomm
20:33:23	ended unit OTAH3112 for requirement HOSEL (>19.7 km) ** Recommended unit AUCKOS
20:33:23	U4 for requirement CANT (>19.7 km) ** Recommended unit WAIA711 for requirement
20:33:23	PUMP (>7.7 km) ** Recommended unit AVON607 for requirement PUMP (>6.4 km)
20:33:32	PA Selcal used to Initiate Alerting. (WEST671 at 1467 WEST HARBOUR 182671)
20:33:32	PA Selcal used to Initiate Alerting. (WEST672 at 1467 WEST HARBOUR 182672)
20:33:32	PA Selcal used to Initiate Alerting. (ELLE274 at 1427 ELLERSLIE 182271)
20:33:32	PA Selcal used to Initiate Alerting. (PARN256 at 1425 PARNELL 182251)
20:33:33	PA Selcal used to Initiate Alerting. (AVON6015 at 1460 AVONDALE 182607)
20:33:33	PA Selcal used to Initiate Alerting. (OTAH3112 at 1431 OTAHUHU 182311)
20:33:33	Pager used to Initiate Alerting.
20:33:33	Station Selcal used to Initiate Alerting. (WAIA711 at 1471 WAIATARUA 182713)
20:33:33	PA Selcal used to Initiate Alerting. (AVON607 at 1460 AVONDALE 182607)
20:33:33	PA Selcal used to Initiate Alerting. (OTAH311 at 1431 OTAHUHU 182311)
20:33:35	Unit AUCKOSU4 failed to contact via Selcal
20:33:35	AC ALREADY RESPONDING AT INITIAL TRANSMIT 2ND ALARM

20:33:42	ALERTING_COMPLETED AUCKOSU4
20:33:42	ALERTING_COMPLETED AUCKOSU4
20:33:46	Unit WAIA711 failed to contact via Selcal
20:33:49	ALERTING_COMPLETED WAIA711
20:33:49	ALERTING_COMPLETED WEST671
20:33:49	ALERTING_COMPLETED WEST672
20:33:52	ALERTING_COMPLETED WEST671
20:33:52	ALERTING_COMPLETED WEST672
20:33:55	ALERTING_COMPLETED ELLE274
20:33:58	ALERTING_COMPLETED PARN256
20:34:02	ALERTING_COMPLETED AVON6015
20:34:02	ALERTING_COMPLETED AVON607
20:34:05	ALERTING_COMPLETED OTAH3112
20:34:05	ALERTING_COMPLETED OTAH311
20:34:09	
20:34:12	Unit WEST671 [K1 : PROCEEDING TO INCIDENT]
20:34:19	FIR2AMB: 3RD ALARM PLEASE RESPOND
20:34:28	FIR2POL: 3RD ALARM PLEASE RESPOND
20:35:30	PA Selcal used to Initiate Alerting. (BALM611 at 1461 BALMORAL 182611)
20:35:30	PA Selcal used to Initiate Alerting. (BALM6117 at 1461 BALMORAL 182611)
20:35:34	ALERTING_COMPLETED BALM611
20:35:35	ALERTING_COMPLETED BALM6117
20:36:14	TO RESPOND AT THIS TIME
20:36:18	Unit BALM611 [K1 : PROCEEDING TO INCIDENT]
20:36:18	** Units excluded from recommendation: AVON607
20:36:21	Unit OTAH3112 [K1 : PROCEEDING TO INCIDENT]
20:36:24	Unit AUCK2018 [K2 : IN ATTENDANCE AT INCIDENT]
20:36:28	Unit ELLE274 [K1 : PROCEEDING TO INCIDENT]
20:36:28	FIR2AMB NO INJURIES AT THIS STAGE FYI
20:36:29	** Units excluded from recommendation: OTAH311
20:36:33	FIR2AMB: AFFIRM WHEN INFO COMES TO HAND
20:36:34	Unit REGION1G [K1 : PROCEEDING TO INCIDENT]
20:36:38	** Units excluded from recommendation: BALM611
20:36:41	FIR2AMB YOUR REPONSE STILL REQUIRED HOWEVER
20:36:45	Unit AVON6015 [K1 : PROCEEDING TO INCIDENT]
20:36:48	Unit PARN256 [K1 : PROCEEDING TO INCIDENT]
20:37:01	Unit TEAT662 [K1 : PROCEEDING TO INCIDENT]
20:37:06	Unit GLEN641 [K2 : IN ATTENDANCE AT INCIDENT]
20:37:45	** Recommended unit GREY261 for requirement CANBACKUP (>9.7 km) ** Recommended

20:37:45	unit AUCK207 for requirement CANBACKUP (>11.6 km) ** Recommended unit WAIT771 f
20:37:45	or requirement PUMP (>8.6 km)
20:37:49	PA Selcal used to Initiate Alerting. (WAIT771 at 1477 WAITAKERE 182771)
20:37:57	Unit BALM6117 [K1 : PROCEEDING TO INCIDENT]
20:37:59	ALERTING_COMPLETED WAIT771
20:38:16	Pager used to Initiate Alerting.
20:38:17	ALERTING_COMPLETED AUCKCITY4
20:38:17	ALERTING_COMPLETED AUCKCITY4
20:38:26	AAC CALLISTER ACK PAGE WILL RESPOND
20:38:28	Unit WEST672 [K1 : PROCEEDING TO INCIDENT]
20:40:03	Unit WAIA711 [K1 : PROCEEDING TO INCIDENT]
20:40:08	Unit WAIA711 [KC : UNIT CALLING]
20:40:25	Unit OTAH311 [K1 : PROCEEDING TO INCIDENT]
20:40:46	
20:40:53	
20:41:19	Unit WEST671 [K2 : IN ATTENDANCE AT INCIDENT]
20:41:26	Unit HEND657 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T X2 - NO RESPONSE
20:41:27	Unit TEAT662 [K2 : IN ATTENDANCE AT INCIDENT]
20:41:49	Unit WAIA711 [SITREP :] ADVISING RESPONDING SFF AND ONE
20:42:32	Unit WAIT771 [K1 : PROCEEDING TO INCIDENT]
20:42:40	Unit WAIT771 [K1 : PROCEEDING TO INCIDENT]
20:43:12	Unit AUCKCITY4 [K1 : PROCEEDING TO INCIDENT]
20:43:33	Unit AUCKCITY4 [K1 : PROCEEDING TO INCIDENT]
20:43:51	Unit AUCK205 [K2 : IN ATTENDANCE AT INCIDENT]
20:44:14	Pager used to Initiate Alerting.
20:44:15	ALERTING_COMPLETED WAITEMATA1
20:44:15	ALERTING_COMPLETED WAITEMATA1
20:44:55	Pager used to Initiate Alerting.
20:44:56	ALERTING_COMPLETED FIWAITEM4
20:44:56	ALERTING_COMPLETED FIWAITEM4
20:45:00	Unit FIWAITEM4 [K1 : PROCEEDING TO INCIDENT]
20:45:12	Unit HEND657 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T X2 NO RESPONSE
20:45:15	Unit WEST672 [K2 : IN ATTENDANCE AT INCIDENT]
20:45:33	Unit AUCKOSU [K7 : AT NORMAL STATION]
20:45:46	Unit AUCK2018 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T NO RESPONSE
20:46:56	Unit AUCKOSU3 [K2 : IN ATTENDANCE AT INCIDENT]
20:47:54	Unit AVON607 [K2 : IN ATTENDANCE AT INCIDENT]
20:48:04	Unit WAITEMATA1 [K1 : PROCEEDING TO INCIDENT]

20:48:08	Unit AVON607 [K2 : IN ATTENDANCE AT INCIDENT]
20:49:57	Unit WAIT771 [KC : UNIT CALLING]
20:50:13	Unit AVON6015 [K2 : IN ATTENDANCE AT INCIDENT]
20:50:15	Unit WAIT771 [SITREP :] DO YOU HAVE A STAGING AREA FOR COUNTDOWN
20:50:32	Unit WAIT771 [COMCEN COM : MESSAGE] NOT AT THIS STAGE CONFIRMING YOU ARE FULLY C
20:50:32	REWED
20:50:40	Unit WAIT771 [SITREP :] CREW OF 6
20:51:18	Unit BALM611 [K2 : IN ATTENDANCE AT INCIDENT]
20:51:33	Unit HEND657 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T NO RESPONSE - EXTERNAL
20:51:33	ALERT APPLIED
20:51:46	Unit WAIA711 [K2 : IN ATTENDANCE AT INCIDENT]
20:52:05	Unit BALM6117 [K2 : IN ATTENDANCE AT INCIDENT]
20:52:23	Pager used to Initiate Alerting.
20:52:23	Phone used to Initiate Alerting.
20:52:24	ALERTING_COMPLETED VSOWAITEM3
20:52:24	ALERTING_COMPLETED VSOWAITEM3
20:52:25	ALERTING_COMPLETED TAKA8019
20:52:31	Unit WAIT771 [K2 : IN ATTENDANCE AT INCIDENT]
20:53:17	Unit ELLE274 [K2 : IN ATTENDANCE AT INCIDENT]
20:54:03	Unit HEND657 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T X2 NO RESPONSE
20:55:04	Unit WAITEMATA1 [SITREP :] HAVE WE GOT A SITREP YET
20:55:18	Unit WAITEMATA1 [COMCEN COM : MESSAGE] NEGATIVE NOT YET - NO RESPONSE TO EXTERNA
20:55:18	L ALERT EITHER
20:55:39	Unit WAITEMATA1 [SITREP :] JUST KEEP TRYING FOR A SITREP
20:56:10	Unit HEND657 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T NO RESPONSE
20:56:21	Unit HEND651 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T NO RESPONSE
20:57:13	Unit AUCK2018 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T NO RESPONSE
20:58:40	FIR2AMB COPY THANK YOU
20:59:00	Unit VSOWAITEM3 [K1 : PROCEEDING TO INCIDENT]
20:59:08	Unit VSOWAITEM3 [K1 : PROCEEDING TO INCIDENT]
20:59:15	Unit OTAH3112 [K2 : IN ATTENDANCE AT INCIDENT]
20:59:41	Unit VSOWAITEM3 [K1 : PROCEEDING TO INCIDENT]
21:00:31	Unit AUCKCITY4 [K2 : IN ATTENDANCE AT INCIDENT]
21:01:32	Unit AUCKCITY4 [COMCEN COM : MESSAGE] WOULD YOU BE ABLE TO CHASE UP THE OIC FOR
21:01:32	A SITREP AND HAVE SOMEONE FROM THE COMMAND UNIT PHONE FIRECOM
21:01:41	Unit VSOWAITEM3 [KC : UNIT CALLING]
21:02:11	Unit VSOWAITEM3 [SITREP :] CAN YOU CONFIRM I AM SHOWING K1 ITS FAILED AT THIS
21:02:11	END AND I AM HEADING TO TAKAPUNA TO UPLIFT UNIFORM TRAILER

21:02:21	Unit WAITEMATA1 [K2 : IN ATTENDANCE AT INCIDENT]
21:02:21	Unit VSOWAITEM3 [COMCEN COM : MESSAGE] AFFIRM K1 2 MINS
21:02:44	Pager used to Initiate Alerting.
21:02:44	Unit AUCKOSU2 failed to contact via Selcal
21:02:45	ALERTING_COMPLETED AUCKOSU2
21:02:47	Unit AUCKOSU2 [K1 : PROCEEDING TO INCIDENT]
21:03:00	Unit AUCKOSU2 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)] W
21:03:00	ITH ABULTIONS TRAILER
21:03:44	Unit HEND657 [KC : UNIT CALLING]
21:04:11	Unit HEND657 [SITREP :] LARGE FIRE IN STOCK IN COUNTDOWN ONE HPD ONE LPD WITH
21:04:11	ONE LPD BEING SET UP BA
21:04:24	Unit AUCKOSU4 [K1 : PROCEEDING TO INCIDENT]
21:04:49	Unit HEND657 [COMCEN COM : MESSAGE] BE ADV THE ABLUTIONS TRAILER AND OSU ARE K1
21:05:15	Unit REGION1G [COMCEN COM : MESSAGE] FIRECOM CALLS VIA R/T X2 - NO RESPONSE
21:08:52	Unit REGION1G [K2 : IN ATTENDANCE AT INCIDENT]
21:09:28	Unit PARN256 [K2 : IN ATTENDANCE AT INCIDENT]
21:12:02	Unit FIWAITEM4 [K2 : IN ATTENDANCE AT INCIDENT]
21:15:47	Unit AUCK2018 [KC : UNIT CALLING]
21:18:00	Unit AUCK2018 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] HENDERSON
21:18:00	COMMAND HAS BEEN SET UP K45 AC
21:20:22	Unit AUCK2018 [COMCEN COM : MESSAGE] CAN SOMEONE FROM THE COMMAND UNIT CONTACT F
21:20:22	IRECOM BY PHONE
21:23:40	Unit AUCKOSU2 [K2 : IN ATTENDANCE AT INCIDENT]
21:33:12	** PFA/CPN search completed
21:33:29	Unit AUCKOSU4 [K2 : IN ATTENDANCE AT INCIDENT]
21:35:20	Alarm Timer Extended: 0
21:35:20	Alarm Timer Extended: 0
21:35:20	Alarm Timer Extended: 0
21:35:21	Alarm Timer Extended: 0
21:35:22	Alarm Timer Extended: 0
21:35:23	Alarm Timer Extended: 0
21:35:23	Alarm Timer Extended: 0
21:35:24	Alarm Timer Extended: 0
21:35:24	Alarm Timer Extended: 0

21:35:24	Alarm Timer Extended: 0
21:35:24	Alarm Timer Extended: 0
21:35:24	Alarm Timer Extended: 0
21:35:25	Alarm Timer Extended: 0
21:43:59	Unit OTAH311 [K2 : IN ATTENDANCE AT INCIDENT]
21:46:37	Unit VSOWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]
21:46:47	Unit VSOWAITEM3 [KC : UNIT CALLING]
21:47:43	AT THE INCIDENT WITH UNIFORM TRAILER CAN
21:47:44	Unit VSOWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] AT THE INCIDENT WITH UNIFORM T
21:47:44	RAILER CAN YOU PUT TAKA8029 K2
21:47:58	Unit AUCK2018 [KC : UNIT CALLING]
21:47:59	Unit VSOWAITEM3 [COMCEN COM : MESSAGE] WHEN YOU SEE SOMEONE FROM THE COMMAND UNI
21:47:59	T COULD YOU ASK THEM TO PHONE FIRECOM
21:48:10	Unit TAKA8019 [K2 : IN ATTENDANCE AT INCIDENT]
21:50:55	Unit AUCK2018 [SITREP :] MESSAGE FROM COMMANDER BUILDING OF 3 FLOORS A
21:50:55	REA UNK AT THE MOMENT USED AS A SHOPPING MALL SUPERMARKET COMPLEX FIRE LOCATED I
21:50:55	N COUNTDOWN SUPERMARKET EQUIPMENT BEING USED 5LPD 2HPD EVALUATING VENTILATION TE
21:50:55	LEMETRY BA INTERNAL OFFENSIVE ATTACK
21:50:58	Unit AUCK2018 [K36 : CONTACT COMMUNICATIONS CENTRE BY PHONE]
21:56:06	Unit AUCK2018 [KC : UNIT CALLING]
21:56:29	Unit AUCK2018 [K12 : SUSPICIOUS FIRE]
21:59:42	Unit AUCK205 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
22:00:18	Unit VSOWAITEM3 [SITREP :] VIA PHONE COMMAND UNIT THE LVL 2 UNIFORM TRAILER IS
22:00:18	ON RAILSIDE JUST DOWN FM THE BA TENDER
22:10:14	Unit AIRAKL3633 [K7 : AT NORMAL STATION]
22:15:32	Unit AUCK2018 [KC : UNIT CALLING]
22:16:43	Unit AUCK2018 [SITREP :] SPINRKLER SYSTEM ISOLATED VENTILATION IN PROGRESS STA
22:16:43	NDING BY TWO DELIVERYS NO FURTHER RESOURCES REQUIRED
22:16:49	Alarm Timer Extended: 0
22:16:50	Alarm Timer Extended: 0
22:16:51	Alarm Timer Extended: 0
22:16:52	Alarm Timer Extended: 0
22:16:53	Alarm Timer Extended: 0
22:19:54	Unit PARN256 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

22:29:29	Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
22:30:33	Unit WAITEMATA1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
22:43:35	Unit WAIT771 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
22:44:53	Unit WEST672 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
22:51:12	Unit OTAH311 [K2 : IN ATTENDANCE AT INCIDENT]
22:51:18	Unit OTAH3112 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
22:51:21	Unit OTAH311 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
23:02:28	Unit ELLE274 [K2 : IN ATTENDANCE AT INCIDENT]
23:02:35	Unit ELLE274 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
23:17:43	Unit TEAT664 [KC : UNIT CALLING]
23:18:02	Unit TEAT664 [K10 : RE-COMMISSIONING APPLIANCE]
23:18:06	Unit HEND657 [KC : UNIT CALLING]
23:18:16	Unit HEND657 [K10 : RE-COMMISSIONING APPLIANCE]
23:19:46	Unit AUCK2018 [COMCEN COM : MESSAGE] FROM ATOC DO YOU STILL REQUIRE GREAT NORTH
23:19:46	ROAD CLOSED
23:20:56	Unit AUCK2018 [SITREP :] STAND BY
23:21:38	Unit AUCK2018 [SITREP :] AFFIRMATIVE YOU CAN RE OPEN THE ROAD
23:26:05	Unit WEST671 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
23:29:28	Unit TEAT662 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
23:39:08	Unit WAIA711 [K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]
23:41:38	Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
23:46:50	Unit GLEN641 [KC : UNIT CALLING]
23:47:11	Unit GLEN641 [K10 : RE-COMMISSIONING APPLIANCE]
23:49:51	Unit HEND651 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
23:50:21	Unit WAIA711 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
23:51:20	Unit AUCK2018 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO
23:57:24	Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:02:14	Unit AUCKOSU3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:02:47	Unit AVON607 [KC : UNIT CALLING]
00:03:15	Unit AVON607 [SITREP :] ALL ROADS AROUND FIRE GROUND HAVE NOW RE OPENED
00:03:30	FIR2POL ALL ROADS AROUND FIRE GROUND HAVE NOW RE OPENED
00:04:51	** Units excluded from recommendation: AUCKOSU
00:04:57	** Units restored to recommendation: AUCKOSU
00:08:41	Unit REGION1G [K6 : ON PAGER (STATE LOCATION)]
00:09:54	Unit AUCKCITY4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:23:17	Unit VSOWAITEM3 [KC : UNIT CALLING]
00:23:41	Unit VSOWAITEM3 [SITREP :] COULD YOU PLACE TAKA8019 K7 ON STATION
00:23:47	Unit TAKA8019 [K7 : AT NORMAL STATION]
00:23:47	Unit AUCK2018 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

00:44:43	Unit VSOWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:48:25	Unit BALM6117 [K7 : AT NORMAL STATION]
00:57:07	Unit AVON607 [KC : UNIT CALLING]
00:57:34	Unit AVON607 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO
00:57:34	ND657
00:57:40	Unit AVON607 [K10 : RE-COMMISSIONING APPLIANCE]
00:57:45	MSU Selcal used to Initiate Alerting. (HEND657 D062E2)
00:57:49	ALERTING_COMPLETED HEND657
00:57:59	FC
00:57:59	Unit HEND657 [K2 : IN ATTENDANCE AT INCIDENT] FC
00:58:21	Unit HEND657 [K2 : IN ATTENDANCE AT INCIDENT]
00:58:34	Unit HEND657 [KC : UNIT CALLING]
00:58:52	Unit HEND657 [K32 : ON RADIO TEST - HOW DO YOU RECEIVE]
00:59:03	Unit BALM611 [K7 : AT NORMAL STATION]
01:06:34	Unit AVON607 [COMCEN COM : MESSAGE] - MANUAL TIME ENTERED 07/05/21 01:06:14 JUST
01:06:34	WANTING TO CONFIRM IS 6015 BACK ON STATION OR AT THE INCIDENT? (THEY ARE BACK O
01:06:34	N STN)
01:06:43	Unit AVON6015 [K7 : AT NORMAL STATION] ENTERED BY FIRECOM
01:06:43	ENTERED BY FIRECOM
01:29:52	** Cross Referenced to Event # F3237533 at: 07/05/21 01:29:52
01:47:12	Unit HEND657 [KC : UNIT CALLING]
01:48:00	Unit HEND657 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM SITREP] SSO
01:48:00	RTHER STANDBYS REQUIRED INCIDENT LEFT WITH POLICE
01:55:34	Unit HEND657 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:25:47	** PFA/CPN search completed
02:44:32	UNIT TAKA8019 RESPONSE TIME [NULL] ADJUSTED TO 20210506214809NS AT 07/05/2021 02
02:44:33	** Assigned Result Code: STRU, Detailed Event Type: 1100
07:04:05	FIRE INVESTIGATION
07:04:28	** Event F3237517 has been reopened at: 07/05/21 07:04:28
07:04:31	** LOI search completed at 07/05/21 07:04:29
07:04:34	Pager used to Initiate Alerting.
07:04:35	ALERTING_COMPLETED FIWAITEM4
07:04:36	ALERTING_COMPLETED FIWAITEM4
07:05:26	T WITH THE POLICE TO INVESTIGATE
07:10:42	Unit FIWAITEM4 [K1 : PROCEEDING TO INCIDENT]
08:12:03	Unit FIWAITEM4 [K2 : IN ATTENDANCE AT INCIDENT]
08:12:29	Unit FIWAITEM4 [COMCEN COM : MESSAGE] WELFARE CHECK AS YOU ARE K1 1HR
08:12:41	Unit FIWAITEM4 [SITREP :] VIA PHONE - JUST ARRIVING

09:21:43 W 09:21:52 Radio used to Initiate Alerting. 09:21:55 ALERTING_COMPLETED FENORTH2 09:22:00 Unit FENORTH2 [K1 : PROCEEDING TO INCIDENT] 09:44:43 Unit FENORTH2 [K2 : IN ATTENDANCE AT INCIDENT] VIA PHONE 09:44:43 Unit FENORTH2 [K2 : IN ATTENDANCE AT INCIDENT] VIA PHONE 10:26:00 Alarm Timer Extended: 0 11:28:52 Unit FIWAITEM4 [COMCEN COM : MESSAGE] VIA PHONE - NO RESPONSE FOR WELFARE CHECK 11:42:23 Pager used to Initiate Alerting. 11:42:24 ALERTING_COMPLETED FIWAITEM3 11:42:23 Pager used to Initiate Alerting. 11:42:24 ALERTING_COMPLETED FIWAITEM3 11:43:09 Unit FIWAITEM3 [SITREP :] (PHONE) - IN ATTENDANCE TO EVENT (STATE EVENT ADDRESS)] 11:43:30 Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE 11:43:34 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:34 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:24:34 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:03:38 Unit FIWAITEM3 [K5 : ON PAGER (STATE LOCATION)] 13:07:52 VIA PHONE 13:07:52 <t< th=""><th>08:53:22</th><th>Alarm Timer Extended: 0</th></t<>	08:53:22	Alarm Timer Extended: 0
 09:21:55 ALERTING_COMPLETED FENORTH2 09:22:00 Unit FENORTH2 [K1 : PROCEEDING TO INCIDENT] 09:44:43 Unit FENORTH2 [K2 : IN ATTENDANCE AT INCIDENT] VIA PHONE 10:26:00 Alarm Timer Extended: 0 11:28:52 Unit FIWAITEM4 [COMCEN COM : MESSAGE] VIA PHONE - NO RESPONSE FOR WELFARE CHECK 11:38:00 Unit FIWAITEM4 [SITREP :] (PHONE) ACK WELFARE CHECK 11:42:23 Pager used to Initiate Alerting. 11:42:24 ALERTING_COMPLETED FIWAITEM3 11:43:09 Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADRESS)] 11:43:09 VIA PHONE 11:43:33 Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE 11:43:34 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 FCOMM 11:43:44 Init FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:03:38 Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 13:07:52 UNIT FINORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGIONIG RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 202105062030909N SAT 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210506203409NS AT 0705/2021 1 	09:21:43	w
 Unit FENORTH2 [K1 : PROCEEDING TO INCIDENT] 9:44:43 Unit FENORTH2 [K2 : IN ATTENDANCE AT INCIDENT] VIA PHONE 9:44:43 Unit FENORTH2 [K2 : IN ATTENDANCE AT INCIDENT] VIA PHONE 10:26:00 Alarm Timer Extended: 0 11:28:52 Unit FIWAITEM4 [COMCEN COM : MESSAGE] VIA PHONE - NO RESPONSE FOR WELFARE CHECK 11:38:00 Unit FIWAITEM4 [SITREP :] (PHONE) ACK WELFARE CHECK 11:42:23 Pager used to Initiate Alerting. 11:42:24 ALERTING_COMPLETED FIWAITEM3 11:43:09 Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)] 11:43:09 UI FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)] 11:43:09 UI FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 I fIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 I thit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:07:52 UI A PHONE 13:07:52 UI A PHONE 13:07:52 UNIT FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203409NS AT 0 15:10:10 UNIT PIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210506203409NS AT 0 07:05/2021 1 	09:21:52	Radio used to Initiate Alerting.
 09:44:43 VIA PHONE 09:44:43 Unit FENORTH2 [K2 : IN ATTENDANCE AT INCIDENT] VIA PHONE 10:26:00 Alarm Timer Extended: 0 11:28:52 Unit FIWAITEM4 [COMCEN COM : MESSAGE] VIA PHONE - NO RESPONSE FOR WELFARE CHECK 11:38:00 Unit FIWAITEM4 [SITREP :] (PHONE) ACK WELFARE CHECK 11:42:23 Pager used to Initiate Alerting. 11:42:24 ALERTING_COMPLETED FIWAITEM3 11:43:09 Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)] 11:43:09 VIA PHONE 11:43:09 VIA PHONE 11:43:33 Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE 11:43:34 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 FCOMM 11:43:44 Init FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 Init FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:07:52 VIA PHONE 13:07:52 VIA PHONE 13:07:52 UNIT FIWAITEM4 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGIONIG RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 2021050620309NS AT 15:10:10 UNIT FARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0 07/05/2021 1 	09:21:55	ALERTING_COMPLETED FENORTH2
09:44:43Unit FENORTH2 [K2 : IN ATTENDANCE AT INCIDENT] VIA PHONE10:26:00Alarm Timer Extended: 011:28:52Unit FIWAITEM4 [COMCEN COM : MESSAGE] VIA PHONE - NO RESPONSE FOR WELFARE CHECK11:38:00Unit FIWAITEM4 [SITREP :] (PHONE) ACK WELFARE CHECK11:42:23Pager used to Initiate Alerting.11:42:24ALERTING_COMPLETED FIWAITEM311:43:09Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]11:43:09VIA PHONE11:43:30Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]11:43:44Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]11:43:44FCOMM11:43:44Init FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM12:24:33Alarm Timer Extended: 012:42:28Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]13:07:52VIA PHONE13:07:52Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]13:07:52UNIT PRINZFIG RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT15:10:09UNIT PRINZFIG RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 015:10:10UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	09:22:00	Unit FENORTH2 [K1 : PROCEEDING TO INCIDENT]
10:26:00Alarm Timer Extended: 011:28:52Unit FIWAITEM4 [COMCEN COM : MESSAGE] VIA PHONE - NO RESPONSE FOR WELFARE CHECK11:38:00Unit FIWAITEM4 [SITREP :] (PHONE) ACK WELFARE CHECK11:42:23Pager used to Initiate Alerting.11:42:24ALERTING_COMPLETED FIWAITEM311:43:09Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]11:43:09VIA PHONE11:43:33Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE11:43:34Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]11:43:44FCOMM11:43:44Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM12:24:33Alarm Timer Extended: 012:42:28Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]13:07:52VIA PHONE13:07:52Unit FEORTH2 [K6 (ON PAGER (STATE LOCATION)] VIA PHONE15:10:09UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT15:10:10UNIT FIWAITEM3 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0	09:44:43	VIA PHONE
11:28:52Unit FIWAITEM4 [COMCEN COM : MESSAGE] VIA PHONE - NO RESPONSE FOR WELFARE CHECK11:38:00Unit FIWAITEM4 [SITREP :] (PHONE) ACK WELFARE CHECK11:42:23Pager used to Initiate Alerting.11:42:24ALERTING_COMPLETED FIWAITEM311:43:09Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]11:43:09VIA PHONE11:43:33Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE11:43:34Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]11:43:44FCOMM11:43:44Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM12:24:33Alarm Timer Extended: 012:42:28Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]13:07:52VIA PHONE13:07:52VIA PHONE13:07:52Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]13:07:52UNIT FEORTH2 [K6 : ON PAGER (STATE LOCATION)]15:10:09UNIT REGIONIG RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT15:10:10UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210506203409NS AT 0	09:44:43	Unit FENORTH2 [K2 : IN ATTENDANCE AT INCIDENT] VIA PHONE
WELFARE CHECK11:38:00Unit FIWAITEM4 [SITREP :] (PHONE) ACK WELFARE CHECK11:42:23Pager used to Initiate Alerting.11:42:24ALERTING_COMPLETED FIWAITEM311:43:09Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]11:43:09VIA PHONE11:43:33Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE11:43:34Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]11:43:44FCOMM11:43:44FCOMM12:24:33Alarm Timer Extended: 012:42:28Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM13:03:38Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]13:07:52VIA PHONE13:07:52VIA PHONE13:07:52Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]15:10:09UNIT REGIONIG RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 202010506203009NS AT15:10:10UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	10:26:00	Alarm Timer Extended: 0
 11:42:23 Pager used to Initiate Alerting. 11:42:24 ALERTING_COMPLETED FIWAITEM3 11:43:09 Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)] 11:43:09 VIA PHONE 11:43:33 Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE 11:43:34 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 FCOMM 11:43:44 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] 13:07:52 VIA PHONE 13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203409NS AT 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1 	11:28:52	
11:42:24ALERTING_COMPLETED FIWAITEM311:43:09Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]11:43:09VIA PHONE11:43:33Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE11:43:34Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]11:43:44FCOMM11:43:44FCOMM12:24:33Alarm Timer Extended: 012:42:28Unit FIWAITEM3 [K2 : ON RT INSIDE NORMAL TURNOUT AREA]13:03:38Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]13:07:52VIA PHONE13:07:52Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE15:10:09UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT15:10:10UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210506203409NS AT 0	11:38:00	Unit FIWAITEM4 [SITREP :] (PHONE) ACK WELFARE CHECK
 11:43:09 Unit FIWAITEM3 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)] 11:43:09 VIA PHONE 11:43:33 Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE 11:43:34 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 FCOMM 11:43:44 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:03:38 Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] 13:07:52 VIA PHONE 13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGIONIG RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203409NS AT 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1 	11:42:23	Pager used to Initiate Alerting.
ADDRESS)]11:43:09VIA PHONE11:43:33Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE11:43:34Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]11:43:44FCOMM11:43:44Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM12:24:33Alarm Timer Extended: 012:42:28Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]13:03:38Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]13:07:52VIA PHONE13:07:52Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE15:10:09UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT15:10:10UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	11:42:24	ALERTING_COMPLETED FIWAITEM3
 11:43:33 Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE 11:43:34 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 FCOMM 11:43:44 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:03:38 Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] 13:07:52 VIA PHONE 13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1 	11:43:09	
 11:43:34 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] 11:43:44 FCOMM 11:43:44 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:03:38 Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] 13:07:52 VIA PHONE 13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 2021050620309NS AT 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1 	11:43:09	VIA PHONE
11:43:44FCOMM11:43:44Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM12:24:33Alarm Timer Extended: 012:42:28Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]13:03:38Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]13:07:52VIA PHONE13:07:52Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE15:10:09UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT15:10:09UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 015:10:10UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	11:43:33	Unit FIWAITEM3 [SITREP :] VIA PHONE - IN ATTENDANCE
 11:43:44 Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM 12:24:33 Alarm Timer Extended: 0 12:42:28 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:03:38 Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] 13:07:52 VIA PHONE 13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT 15:10:09 UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1 	11:43:34	Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]
12:24:33Alarm Timer Extended: 012:42:28Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]13:03:38Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]13:07:52VIA PHONE13:07:52Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE15:10:09UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT15:10:09UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 015:10:10UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	11:43:44	FCOMM
 12:42:28 Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] 13:03:38 Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] 13:07:52 VIA PHONE 13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT 15:10:09 UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1 	11:43:44	Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT] FCOMM
13:03:38 Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)] 13:07:52 VIA PHONE 13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT 15:10:09 UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	12:24:33	Alarm Timer Extended: 0
13:07:52 VIA PHONE 13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT 15:10:09 UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	12:42:28	Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:07:52 Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE 15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT 15:10:09 UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	13:03:38	Unit FIWAITEM3 [K6 : ON PAGER (STATE LOCATION)]
15:10:09 UNIT REGION1G RESPONSE TIME 06/05/2021 20:36:34 ADJUSTED TO 20210506203009NS AT 15:10:09 UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	13:07:52	VIA PHONE
20210506203009NS AT 15:10:09 UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	13:07:52	Unit FENORTH2 [K6 : ON PAGER (STATE LOCATION)] VIA PHONE
AT 0 15:10:10 UNIT FIWAITEM3 RESPONSE TIME [NULL] ADJUSTED TO 20210507114334NS AT 07/05/2021 1	15:10:09	
07/05/2021 1	15:10:09	UNIT PARN256 RESPONSE TIME 06/05/2021 20:36:48 ADJUSTED TO 20210506203409NS AT 0
15:10:11 ** Assigned Result Code: STRU, Detailed Event Type: 1100	15:10:10	
	15:10:11	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident

CAD Number

F3237517

Incident Controller

Incident Reporter

Distance Travelled (km)

Delay In Receiving Call

Property Details

Occupant

Countdown Supermarket

Building OwnerOwner occupiedGeneral Property UseShop, Mall, Supermarket, Gas station, Sales, OtherSpecial Property UseSupermarket: Over 1000 m2

Purpose Group

Actions Hicia Information **Persons Reported** Trapped **Evacuation Status** Fully evacuated Action Prior 1 **Action Prior 2** Action Taken Extinguishment and ventilation Civilians **Civilians Rescued** 0 **Civilians Extricated** 0 **Civilians Assisted** 0 **Civilians Evacuated** 0 Origin Location Showroom, Sales area Level Ground level Equipment Used Quantity Equipment Hose reel, high pressure delivery 1 3 Low pressure delivery Equipment Involved Equipment Involved Year Make Model

Fire

Arrival Condition Heat Source Large fire Cigarettes, matches and candles - Other

Termination Stage

First Object Ignited

First Object Material

Second Object Ign	itod					
Second Object Ign						
Indicated Cause		Unlawful				
Certainty of Cause		High				
Age of Person		Persons:				
Ethnicity		Unknown				
Gender						
FAIP Service Offer	ed	Unknown				X
						5
					Y Y	
Alarms	Continue	10.7				
Type of Alarm Initiating Call	Sprink	ler			× O	
Performance of System	Alerteo	d occupants - detect	or in room o	f origin	0.2	
Failure/Ineffectiven ess of system				103		
Number of sprinkler heads operated						4
Comments			O ^r			
			0	5/12/2021 10:55:41 AM	Reporter Com	ments
Advised of video sh	owing p	person/s unknown st	arting fire in	chip aisle (Aisle 6)		
			•			
		201		5/13/2021 2:25:22 PM	Reporter Com	ments
FSO Requested at	incident	F3237517 on 06 Ma	ay 2021			
		\mathbf{O}			Nick L	inton
Released at	,e0					