SMS Incident Report

30/05/2017 08:16:24

Summary

CAD Number F2310756

Status

First Caller Contact

Station Papatoetoe Station

Incident Started 20/05/2017 19:04:13

Incident Ended 20/05/2017 20:20:56

Incident Type 1101: Structure fire with damage

Common Name

Address 518 MASSEY ROAD MANGERE

Alarm Method 111 Telephone Alarm Level

PFA Number

Zone 143509

Map Grid E 1761608 Map Grid N 5906372


First Caller

Incident Closed 20/05/2017 21:05:41

Report Completed

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
PAPA344	PM	19:04:53 20 May 2017	19:06:49 20 May 2017	19:12:06 20 May 2017	20:22:38 20 May 2017
MANG351	P1	19:11:09 20 May 2017	19:11:10 20 May 2017	19:12:49 20 May 2017	20:21:13 20 May 2017
AUCKOSU1	SV	19:13:40 20 May 2017	19:14:09 20 May 2017	19:20:44 20 May 2017	20:25:18 20 May 2017
OTAH311	P1	19:04:55 20 May 2017	19:06:03 20 May 2017	19:23:39 20 May 2017	19:39:49 20 May 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
PAPA344	00:00:40	00:07:13	00:07:53	01:18:25
MANG351	00:06:56	00:01:40	00:08:36	01:17:00
AUCKOSU1	00:09:27	00:07:04	00:16:31	01:21:05

SMS Incident Report F2310756 2/8 30/05/2017 08:16:24

OTAH311	00:00:42	00:18:44	00:19:26	00:35:36

Notifications

Date	Time	Party Notified
20 May 2017	19:12:19	SM NORTHCOM RE K99
20 May 2017	19:12:46	VECTOR - ON HOLD
20 May 2017	19:13:26	OSU AUCKLAND
20 May 2017	19:13:50	AAC COUNTIES MANUKAU / AAC MACKERETH - K99 ARRIVAL/PERSONS REPORTED
20 May 2017	19:14:12	VECTOR - WILL CALL BACK WITH AN ETA
20 May 2017	19:16:18	AAC DELFOS ACK PAGER
20 May 2017	19:17:50	COUNTIES 3 ACK PAGE - SITREP REQUIRED. WILL RESPOND IF REQUIRED
20 May 2017	19:18:55	AAC COUNTIES MANUKAU / AAC MACKERETH RE-SITREP
20 May 2017	19:19:52	AAC MACKERETH ACK PAGER
20 May 2017	19:28:49	AAC COUNTIES MANUKAU / AAC MACKERETH - ALL PERSONS ACCOUNTED FOR PER PAGER

Message Log

wessage Log	
Time	Message
19:04:34	INC INFO: SLEEPOUT ON FIRE
19:04:34	MULTIPLE SUBSCRIBERS FOR CALLER NUMBER 92756482. TESA LOOKUP RECOMMENDED.
19:04:35	** LOI search completed at 20/05/17 19:04:35
19:04:46	** Recommended unit PAPA344 for requirement PUMP (>5.2 km)
19:04:46	** Recommended unit OTAH311 for requirement PUMP (>4.5 km)
19:05:00	EVERYONE IS OUT
19:05:57	CALLER BELIEVES FLATMATES THAT STAY IN IT ARE OUT, MAY HAVE LEFT HEATER ON
19:06:03	Unit OTAH311 [K1 : PROCEEDING TO INCIDENT]
19:06:33	INC INFO: HOUSE FIRE
19:06:33	Duplicate Event:Location = 518 MASSEY RD,MANGERE,AUCKLAND, Type = STRU -
19:06:33	STRUCTURE FIRE, Caller Ph Number = , Call Source = 111Inc InfoHOUSE
19:06:33	FIRE, Event Source = Fire 111
19:06:33	End of Duplicate Event data
19:06:50	Unit PAPA344 [K1 : PROCEEDING TO INCIDENT]
19:07:03	INC INFO: SMOKE IN THE VICINITY
19:07:03	Duplicate Event:Location = 2 TIDAL RD,MANGERE,AUCKLAND, Type = MIN - MINOR,
19:07:03	Duplicate Event:Location = 518 MASSEY RD,MANGERE,AUCKLAND, Type = STRU -
19:07:03	INC INFO: FIRE NEXT DOOR
19:07:03	Caller Name =, Caller Ph Number =, Call Source = 111Inc
19:07:03	STRUCTURE FIRE, Caller Name = Caller Ph Number = Call Source
19:07:03	InfoSMOKE IN THE VICINITY, Event Source = Fire 111
	·

SMS Incident Report	F2310756 3/8 30/05/2017 08:16:3	24
19:07:03	= 111Inc InfoFIRE NEXT DOOR , Event Source = Fire 111	
19:07:03	End of Duplicate Event data	
19:07:03	End of Duplicate Event data	
19:08:48	Duplicate Event:Location = TIDAL RD,MANGERE,AUCKLAND, Type = MIN - MINOR, Caller	
19:08:48	INC INFO: SMOKE IN VICINITY	
19:08:48	MULTIPLE SUBSCRIBERS FOR CALLER NUMBER . TESA LOOKUP RECOMMENDED.	
19:08:48	Name =, Caller Ph Number =, Caller Address =	
19:08:48	MASSEY ROAD, MANGERE, AUCKLAND CITY, Call Source = 111Inc InfoSMOKE IN VICINITY,	
19:08:48	Event Source = Fire 111	
19:08:48	End of Duplicate Event data	
19:09:05	Unit PAPA344 [COMCEN COM : MESSAGE] MULTIPLE CALLS. NEAREST HYDRANT OPP 520	
19:09:05	MASSEY RD, 200 MLS	
19:09:18	Duplicate Event:Location = MASSEY RD,MANGERE,AUCKLAND, Type = STRU - STRUCTURE	
19:09:18	INC INFO: SMOKE IN VICINITY	
19:09:18	FIRE, Caller Name = , Caller Ph Number = , Caller Address =	
19:09:18	TELECOM CELLULAR 027, AHURIRI, NAPIER CITY, Call Source = 111Inc InfoSMOKE IN	
19:09:18	VICINITY , Event Source = Fire 111	
19:09:18	End of Duplicate Event data	
19:10:05	Duplicate Event:Location = MASSEY RD,/TIDAL RD,MANGERE,AUCKLAND, Type = MIN -	
19:10:05	INC INFO: FIRE IN VICINITY	
19:10:05	MINOR, Caller Name = , Caller Ph Number = , Call Source =	
19:10:05	111Inc InfoFIRE IN VICINITY, Event Source = Fire 111	
19:10:05	End of Duplicate Event data	
19:10:08	Duplicate Event:Location = 14 ROCK DAISY CR,MANGERE,AUCKLAND, Type = STRU -	
19:10:08	INC INFO: HOUSE FIRE	
19:10:08	STRUCTURE FIRE, Caller Ph Number = , Call Source = 111Inc InfoHOUSE	
19:10:08	FIRE, Event Source = Fire 111	
19:10:08	End of Duplicate Event data	
19:11:10	Unit MANG351 [K1 : PROCEEDING TO INCIDENT]	
19:11:17	Unit MANG351 [K1 : PROCEEDING TO INCIDENT]	
19:11:52	Duplicate Event:Location = MASSEY RD,/TIDAL RD,MANGERE,AUCKLAND, Type = STRU -	
19:11:52	CALLER SAYS THEY CAN ACCESS FROM 4A TIDAL ROAD (LONG DRIVEWAY)	
19:11:52	STRUCTURE FIRE, Caller Name =, Caller Ph Number =, Call	
19:11:52	INC INFO: SLEEPOUT ON FIRE	
19:11:52	Source = 111Inc InfoSLEEPOUT ON FIRE , Event Source = Fire 111	
19:11:52	End of Duplicate Event data	
19:11:53	Duplicate Event:Location = 4 TIDAL RD,MANGERE,AUCKLAND, Type = STRU - STRUCTURE	
19:11:53	INC INFO: HOUSE FIRE	
19:11:53	FIRE, Caller Ph Number =, Call Source = 111Inc InfoHOUSE FIRE, Event	
19:11:53	Source = Fire 111	

Swis incluent Report	12310730 4/6 30/03/2017 00:10	.44
19:11:53	End of Duplicate Event data	
19:12:06	Unit PAPA344 [K99 : PROPERTY FIRE WELL INV] VERBAL	
19:12:14	Unit PAPA344 [K99 : PROPERTY FIRE WELL INV]	
19:12:19	Unit PAPA344 [KP : PRIORITY MESSAGE]	
19:12:50	Unit MANG351 [K2 : IN ATTENDANCE AT INCIDENT]	
19:12:52	FIR2POL - POSSIBLY PERSONS REPORTED	
19:12:53	Unit PAPA344 [KP : PRIORITY MESSAGE] POSSIBLE PERSONS REPORTED	
19:13:08	FIR2AMB - POSSIBLE PERSONS REPORTED	
19:13:15	Unit PAPA344 [COMCEN COM : MESSAGE] WE WERE ADVISED ON THE FIRST CALL FROM 51	18
19:13:15	MASSEY RD ALL PERSONS WERE BELIEVED TO BE OUT	
19:13:27	AMBO EVENT 0723-1-2017/05/20-FIR LINKED AT 20/05/2017 19:13:27	
19:13:50	Unit AUCKOSU1 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]	
19:13:55	Unit AUCKOSU1 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]	
19:14:04	Duplicate Event:Location = 4 TIDAL RD,MANGERE,AUCKLAND, Type = STRU - STRUCTURE	
19:14:04	INC INFO: HOUSE FIRE	
19:14:04	FIRE, Caller Ph Number = , Call Source = 111Inc InfoHOUSE FIRE, Event	
19:14:04	Source = Fire 111	
19:14:04	End of Duplicate Event data	
19:14:07	INC INFO: FIRE IN VICINITY	
19:14:07	Duplicate Event:Location = ROCK DAISY CR,MANGERE,AUCKLAND, Type = MIN - MINOR,	
19:14:07	Caller Name =, Caller Ph Number =, Call Source = 111Inc	
19:14:07	InfoFIRE IN VICINITY, Event Source = Fire 111	
19:14:07	End of Duplicate Event data	
19:14:10	Unit AUCKOSU1 [K1 : PROCEEDING TO INCIDENT]	
19:14:13	AMBO update to 0723-1-2017/05/20-FIR:	
19:14:14	Location = 518 Massey Rd,MANGERE,	
19:14:14	Caller Name =/, Caller Address = 518 MASSEY ROAD, MANGERE,	
19:14:14	AUCKLAND CITY, Caller Phone = , Headline = SLEEPOUT ON FIRE	
19:14:16	Problem changed to: ORANGE - 40E04 POLICE/FIRE STANDBY	
19:14:54	[FIR] AMB2FIRE copy	
19:15:06	** Event Type changed from FIR2POL to 1F(2) at: 20/05/17 19:15:06	
19:16:12	POLICE COPY	
19:16:44	[FIR] AMB2FIRE responding from manukau	
19:16:55	Unit OTAH311 [COMCEN COM : MESSAGE] FCOMMS CALLS X 2	
19:17:10	Unit PAPA344 [KC : UNIT CALLING]	
19:18:04	Unit PAPA344 [SITREP :] SO WILLIAMS. SLEEPOUT ATTACHED TO HOUSE WI IN FIRE.	
19:18:04	APPROX 4M X 4M. EXTERNAL FIRE ATTACK WITH ONE HPD. K11 POLICE AS WE HAVE A	
19:18:04	FEEDER ACROSS TIDAL RD	
19:18:34	Unit PAPA344 [K11P : POLICE REQUIRED] AS WE HAVE A FEEDER ACROSS TIDAL RD	
19:18:59	Unit PAPA344 [COMCEN COM : MESSAGE] CALLER AT 4A TIDAL RD ADVISES YOU CAN GAIN	I
•	·	

SMS incident Report	F2310/56 5/8 30/05/2017 08:16:24
19:18:59	ACCESS UP THEIR LONG DRIVEWAY TO THE BACK OF 518 MASSEY RD
19:19:05	=======================================
19:19:26	FIR2POL : POLICE ALSO REQUESTED TO ASSIST AS BRIGADE HAVE A HOSE ACROSS THE ROAD
19:19:26	ON TIDAL ROD
19:19:28	=======================================
19:20:44	Unit AUCKOSU1 [K2 : IN ATTENDANCE AT INCIDENT]
19:21:19	
19:21:30	FIRE AND AMBOS ARE 10/7
19:21:39	POLICE 10/7 - 1919HRS
19:23:22	Unit PAPA344 [COMCEN COM : MESSAGE] IS OTAH311 IN ATTENDANCE
19:23:27	Unit PAPA344 [SITREP :] AFFIRM
19:23:40	Unit OTAH311 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FCOMMS AS PER PAPA344
19:23:40	CONFIRMATION
19:24:02	Unit OTAH311 [K2 : IN ATTENDANCE AT INCIDENT]
19:25:30	UK IF ANYONE STILL INSIDE
19:27:01	Unit PAPA344 [KC : UNIT CALLING]
19:27:22	Unit PAPA344 [SITREP :] ALL PERSONS ACCOUNTED FOR
19:27:33	FIR2AMB : UNIT PAPA344 [SITREP :] ALL PERSONS ACCOUNTED FOR
19:27:36	FIR2POL : UNIT PAPA344 [SITREP :] ALL PERSONS ACCOUNTED FOR
19:27:39	
19:39:35	Incident Closed. Reason: 805 Police / Fire Standby
19:39:35	** Cancel Event:Event Canceled by InterCAD
19:39:50	Unit OTAH311 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
20:20:38	Unit PAPA344 [KC : UNIT CALLING]
20:20:57	Unit PAPA344 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
20:21:16	Unit MANG351 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:22:16	Unit PAPA344 [KC : UNIT CALLING]
20:22:39	Unit PAPA344 [K10 : RECOMMISSIONING]
20:23:05	Unit PAPA344 [SITREP :] K10, RETURNING TO STATION
20:25:20	Unit AUCKOSU1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:50:05	BUSINESS RULE CHECKS CANCELLED AT 20/05/17 20:50:05
21:05:40	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
21:05:40	UNIT MANG351 ALERT TIME [NULL] ADJUSTED TO
21:05:40	Qualifier 2:

Incident

CAD NumberF2310756Incident ReporterRoy WilliamsIncident ControllerRoy Williams

Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant

Building Owner Owner occupied

General Property Use Flat, Apartment, Home unit

Special Property Use Flats, Apartments, Units 1 to 2

Purpose Group

Actions

Persons Reported Trapped No

Evacuation Status Not occupied at time of incident

Action Prior 1 Action Prior 2

Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued

Civilians Extricated

Civilians Assisted

Civilians Evacuated

Origin

Location Garage, Carport, Vehicle storage, Storage Shed

Level Ground level

Equipment Used

Equipment
Hose reel, high pressure delivery
BA set
Ladder
Salvage/ventilation: PPV, Fan
Thermal Imaging Camera
Lighting/lights/lighting apparatus
Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Totally involved fire

Heat Source Information not recorded/Unknown

Termination Stage Smoulder

First Object Ignited Cabinetry eg. Desks, Tables, Drawers,

Shelving, Wardrobe, Piano

First Object Material Wood: sawn, finished timber

Second Object Ignited Bedding eg. Mattress, Pillow

Second Object Material Polyurethane eg. Furnishings, Upholstery,

Mattresses

Indicated Cause Undetermined

Certainty of Cause Medium

Age of Person Persons: 17 - 64 yrs

Ethnicity Unknown
Gender Female

FAIP Service Offered No FAIP Service Accepted No

Alarms

Type of Alarm Initiating Call Domestic Smoke Alarms

Performance of System Detector in room of origin - not classified above

Failure/Ineffectiveness of

system

Unknown

Number of sprinkler heads

operated

Structure

Area of One Floor

Age of Building Unknown

Structural Frame Type Metal frame protected

Number of Floors 1

Number of Basements 0

Internal Wall Lining Unknown
Ceiling Lining Unknown

Material Generating Most Flame Polystyrene, Foam plastic

Material Generating Most Smoke Vinyl, Plastic coated fabrics, Upholstery fabircs

Avenue of Flame Travel Stored material

Avenue of Smoke Travel Interior window failure

Extent of Flame Damage Confined to structure of origin

SMS Incident Report F2310756	8/8	30/05/2017 08:16:24
Area of Flame Damage		9
Extent of Smoke Damage	Confined to structure of origin	
Area of Smoke Damage		9
Extent of Water Damage	Confined to structure of origin	
Area of Water Damage		9
Extent of Fire Control Damage	Extended beyond structure of origin	
Area of Fire Control Damage		9

Comments

Post fire investigation revealed no obvious cause of fire. Tennant was unable to be contacted but returned a call the following day. She Reporter Comments

Solve Stated that Roy Williams

Solve Solv

Roy Williams