# **SMS Incident Report**

20/10/2017 09:13:25

**Summary** 

CAD Number F2399021 Status Closed

**Station** Albany Station

Incident Started 18/10/2017 01:55:38 Incident Ended 18/10/2017 03:33:54

Incident Type 1101: Structure fire with damage

**Common Name** 

Address 44 OAKWAY DRIVE SCHNAPPER ROCK

Alarm Method 111 Telephone Alarm Level 1

**PFA Number** 

**Zone** 148534

Map Grid E 1750940 Map Grid N 5931166


First Caller First Caller Contact

Incident Closed 18/10/2017 04:02:36

**Report Completed** 18:34, Thur 19 Oct 2017 by Athol Conway

#### Responses

-					
Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
ALBA851	P1	01:56:52 18 Oct 2017	02:00:03 18 Oct 2017	02:02:04 18 Oct 2017	03:34:20 18 Oct 2017
TAKA807	PR	01:56:55 18 Oct 2017	01:58:18 18 Oct 2017	02:04:33 18 Oct 2017	02:44:42 18 Oct 2017
GREE841	P1	01:56:49 18 Oct 2017	02:01:51 18 Oct 2017	02:07:27 18 Oct 2017	02:28:30 18 Oct 2017
AUCKOSU2	SV	02:14:27 18 Oct 2017	02:14:31 18 Oct 2017	02:34:53 18 Oct 2017	02:55:44 18 Oct 2017
FIAKCITY3	FSO	02:29:01 18 Oct 2017			02:56:03 18 Oct 2017
				i	



# **Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
ALBA851	00:01:14	00:05:12	00:06:26	01:38:42
TAKA807	00:01:17	00:07:38	00:08:55	00:49:04

SMS Incident Report	F2399021	2/8	20/10/2017 09:13:25
---------------------	----------	-----	---------------------

GREE841	00:01:11	00:10:38	00:11:49	00:32:52
AUCKOSU2	00:18:49	00:20:26	00:39:15	01:00:06
FIAKCITY3	00:33:23			01:00:25

# **Notifications**

Date	Time	Party Notified
18 Oct 2017	02:04:18	AAC WAITEMATA GROUP
18 Oct 2017	02:04:27	OSU AUCKLAND
18 Oct 2017	02:07:33	AAC BOOTH ACK PAGE - REPAGE ONLY IF ESCALATES
18 Oct 2017	02:34:09	FIAKCITY3 (JASON GOFFIN) ACK PAGE - TRANSFERRED TO ALBA851
18 Oct 2017	02:55:41	FIAKCITY3 (JASON GOFFIN) - HAS LIASED WITH ALBA851 - ARE GOING TO PUT A

#### Message Log

01:56:19 INC INFO: HOUSE FIRE 01:56:19 MULTIPLE SUBSCRIBERS FOR CALLER NUMBER . TESA	
01:56:19 MULTIPLE SUBSCRIBERS FOR CALLER NUMBER . TESA	
	LOOKUP RECOMMENDED.
01:56:22 ** LOI search completed at 18/10/17 01:56:22	
01:56:31 INC INFO: CAR FIRE	
01:56:31 Duplicate Event:Location = 42 OAKWAY DR,SCHNAPPER ROCK,AUCK	KLAND, Type = MIN -
01:56:31 MINOR, Caller Name = , Caller Ph Number =	, Caller
01:56:31 Address = 42 OAKWAY DRIVE, SCHNAPPER ROCK, AUCKLAND CITY	Y, Call Source = 111Inc
01:56:31 InfoCAR FIRE, Event Source = Fire 111	
01:56:31 End of Duplicate Event data	
01:56:37 ** Recommended unit ALBA851 for requirement PUMP (>1.2 km)	
01:56:37 ** Recommended unit GREE841 for requirement PUMP (>3.2 km)	
01:56:37 ** Recommended unit TAKA807 for requirement CANBACKUP (>5.5 km	n)
01:58:18 Unit TAKA807 [ K1 : PROCEEDING TO INCIDENT]	
01:58:24 Duplicate Event:Location = 44 OAKWAY DR,SCHNAPPER ROCK,AUCK	KLAND, Type = MIN -
01:58:24 INC INFO: CAR FIRE	
01:58:24 MINOR, Caller Name = , Caller Ph Number = , C	Caller Address =
01:58:24 98 LNP FICT,, Call Source = 111Inc InfoCAR FIRE , Event Source = Fire	e 111
01:58:24 End of Duplicate Event data	
01:58:32 Duplicate Event:Location = OAKWAY DR,SCHNAPPER ROCK,AUCKLA	AND, Type = STRU -
01:58:32 INC INFO: CAR CRASHED INTO HOUSE AND HOUSE ON FIRE	
01:58:32 STRUCTURE FIRE, Caller Ph Number = , Call Source =	111Inc InfoCAR
01:58:32 CRASHED INTO HOUSE AND HOUSE ON FIRE, Event Source = Fire 1	111
01:58:32 End of Duplicate Event data	
01:58:36 *	

SMS Incident Report	F2399021 3/8 20/10/2017 09:13:25
01:58:47	COVERING UNIT DEVO811 DISPATCHED TO STATION TAKAPUNA
01:58:47	D0710065
01:59:09	AMBO EVENT 0042-1-2017/10/18-FIR LINKED AT 18/10/2017 01:59:09
01:59:24	FIR2POL: CAR V HOUSE & CAR NOW ON FIRE
01:59:35	FIR
01:59:56	CALLER SAYING CAR GONE UP DRIVEWAY, INTO GARAGE AND CAUGHT ALIGHT, FRONT OF
01:59:56	HOUSE ON FIRE ALSO
02:00:04	Unit ALBA851 [ K1 : PROCEEDING TO INCIDENT]
02:00:06	INC INFO: CAR FIRE
02:00:06	Duplicate Event:Location = 44 OAKWAY DR,SCHNAPPER ROCK,AUCKLAND, Type = STRU -
02:00:06	STRUCTURE FIRE, Caller Name = , Caller Ph Number =
02:00:06	, Caller Address = LAUREL OAK DRIVE, SCHNAPPER ROCK, AUCKLAND CITY,
02:00:06	Call Source = 111Inc InfoCAR FIRE, Event Source = Fire 111
02:00:06	End of Duplicate Event data
02:00:35	INC INFO: HOUSE AND CAR FIRE
02:00:35	Duplicate Event:Location = 35 OAKWAY DR,SCHNAPPER ROCK,AUCKLAND, Type = STRU -
02:00:35	STRUCTURE FIRE, Caller Ph Number = Call Source = 111Inc InfoHOUSE
02:00:35	AND CAR FIRE, Event Source = Fire 111
02:00:35	End of Duplicate Event data
02:00:44	HYDRANT OPPOSITE 44 OAKWAY DR - 150 ML - AND OUTSIDE 31 OAKWAY 150ML
02:00:52	CALLER SAYING HER NEIGHBOURS ARE OUT OF THE HOUSE THAT'S ON FIRE, BUT STATUS OF
02:00:52	CAR OCCUPANTS UNKNOWN
02:01:51	Unit GREE841 [ K1 : PROCEEDING TO INCIDENT]
02:02:05	Unit ALBA851 [ K99 : PROPERTY FIRE WELL INV]
02:03:32	FIR2POL FIRE JUST ARRIVED WILL PASS SHORTLY
02:04:33	Unit TAKA807 [ K2 : IN ATTENDANCE AT INCIDENT]
02:05:32	Unit ALBA851 [ KC : UNIT CALLING]
02:06:52	Unit ALBA851 [ SITREP : ] SO CONWAY 1 CAR FIRE AND FRONT OF SHED WELL INV 2 HP
02:06:52	IN USE
02:07:12	Unit ALBA851 [COMCEN COM : MESSAGE] CAN YOU PASS THE REGO
02:07:28	Unit GREE841 [ K2 : IN ATTENDANCE AT INCIDENT]
02:09:03	WAITEMATA3 VAUGHAN MACKERETH ACK PAGE - DETAILS PASSED
02:14:32	Unit AUCKOSU2 [ K1 : PROCEEDING TO INCIDENT]
02:27:05	Unit ALBA851 [ KC : UNIT CALLING]
02:27:34	Unit ALBA851 [ SITREP : ] POLICE IN ATT STOLEN CAR ON SITE K11 FS
02:28:21	INC INFO: CAR FIRE INTO HOUSE TOC 0156 TOA 0202
02:28:31	Unit GREE841 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
02:33:32	Unit ALBA851 [ KC : UNIT CALLING]
02:34:54	Unit AUCKOSU2 [ K2 : IN ATTENDANCE AT INCIDENT]

SMS Incident Rep	ort F2399021	4/8	20/10/2017 09:13:25
02:44:43	Unit TA	KA807 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	

02:44:43	Unit TAKA807 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
02:55:41	SCENE GUARD ON AT INCIDENT AND WILL RETURN IN THE MORNING
02:55:46	Unit AUCKOSU2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:56:04	Unit FIAKCITY3 [ K6 : ON TELEPAGER]
02:56:05	Unit FIAKCITY3 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:10:19	Unit ALBA851 [ KC : UNIT CALLING]
03:10:40	Unit ALBA851 [ K12 : SUSPICIOUS FIRE]
03:10:48	Unit ALBA851 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
03:32:13	Unit ALBA851 [ KC : UNIT CALLING]
03:33:54	Unit ALBA851 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] FIRE RISK
03:33:54	MANAGEMENT WILL BE RENDEVOUSING WITH CBI IN THE MORNING POLICE HAVING SCENE
03:33:54	GUARD OVERNIGHT
03:34:22	Unit ALBA851 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:02:36	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
04:02:36	Qualifier 2:

#### **Incident**

CAD Number F2399021
Incident Reporter Athol Conway
Incident Controller A Conway
Distance Travelled (km) 4

# **Property Details**

**Delay In Receiving Call** 

Occupant unknown

Building Owner Owner occupied

General Property Use Single house

Special Property Use Single house

**Purpose Group** 

#### **Actions**

Persons Reported Trapped No

**Evacuation Status** Fully evacuated

Action Prior 1
Action Prior 2

Action Taken Extinguishment and ventilation

#### **Civilians**

Civilians Rescued 0

**SMS Incident Report F2399021** 5/8 **20/10/2017 09:13:25** 

Civilians Extricated 0

Civilians Assisted 0

**Civilians Evacuated** 

Origin

**Location** Garage, Carport, Vehicle storage, Storage Shed

Level Ground level

## **Equipment Used**

Quantity		Equipment	
2	Hose reel, high pressure delivery		X

#### **Equipment Involved**

**Equipment Involved** 

Year

Make

Model

**Fire** 

Arrival Condition Large fire

**Heat Source** Exposure fire: Direct burning (convection

currents)

Termination Stage Flame

First Object Ignited Exterior trim eg. Doors, Porches, Decks

First Object Material Wood: sawn, finished timber

Second Object Ignited

**Second Object Material** 

Indicated Cause Unlawful
Certainty of Cause High
Age of Person Unknown
Ethnicity Unknown

Gender

FAIP Service Offered No FAIP Service Accepted No

#### **Alarms**

Type of Alarm Initiating Call Smoke Detector/Security Alarm System

Performance of System Did not operate - detector not in room of origin

Failure/Ineffectiveness of

system

Detector not in room of origin

Number of sprinkler heads operated

#### Structure

Area of One Floor		280
Age of Building	2006 onwards	
Structural Frame Type	Timber frame protected	
Number of Floors		2
Number of Basements		0
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)	
Material Generating Most Flame	Rubber	
Material Generating Most Smoke	Rubber	
Avenue of Flame Travel	No travel	
Avenue of Smoke Travel	Structural factor allowing vertical travel - not classified above	
Extent of Flame Damage	Confined to object of origin	
Area of Flame Damage		15
Extent of Smoke Damage	Confined to structure of origin	
Area of Smoke Damage		280
Extent of Water Damage	No damage of this type	
Area of Water Damage		0
Extent of Fire Control Damage	Confined to object of origin	
Area of Fire Control Damage		15

# **Mobile**

Vehicle Type Car, Taxi, Ambulance

**Licence Plate** 

Year

Make nissar Model terran **Exposure Number 1** 

**Incident Type** 1201: Car, Van, Truck, Boat, Plane, Train fire

**Address** 44 OAKWAY DRIVE SCHNAPPER ROCK

**Distance Exposure Travelled** 

**Surface Material of Exterior Wall** 

**Construction Material of Roof** 

**Method of Heat Transfer** 

## **Property Details**

**Occupant** 

**Building Owner** 

**General Property Use** Single house **Special Property Use** Single house

**Purpose Group** 

#### **Actions**

**Persons Reported Trapped** 

No

**Evacuation Status** 

**Action Prior 1 Action Prior 2** 

**Action Taken** Extinguishment and ventilation

#### **Civilians**

**Civilians Rescued** 0 **Civilians Extricated** 0 **Civilians Assisted** 0

**Civilians Evacuated** 

#### Origin

Location

Passenger area (of transportation equipment)

Level

#### **Equipment Used**

Quantity	Equipment
2	Hose reel, high pressure delivery

#### **Equipment Involved**

**Equipment Involved** 

Year

Make

Model

Fire

Arrival Condition Totally involved fire

Heat Source Unable to classify

Termination Stage Flame

First Object Ignited Flammable liquid and gases (not aerosols or

propellants)

First Object Material Petrol

Second Object Ignited Second Object Material

Indicated CauseUnlawfulCertainty of CauseHighAge of PersonUnknownEthnicityUnknown

Gender

FAIP Service Offered No FAIP Service Accepted No

### Mobile

Vehicle Type Car, Taxi, Ambulance

**Licence Plate** 

Year

Make nissan
Model terrand