

SMS Incident Report

22/05/2023 14:18:46


Summary

CAD Number F2058799 **Status** Closed
Station Hamilton Station
Incident Started 15/04/2016 01:45:17 **Incident Ended** 15/04/2016 05:29:16
Incident Type 1101: Structure fire with damage
Common Name
Address 17 WELLINGTON STREET HAMILTON EAST
Alarm Method 111 Telephone **Alarm Level** 2
PFA Number
Zone 164128
Map Grid E 1801895 **Map Grid N** 5814392
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 15/04/2016 07:54:43
Report Completed 16:54, Tue 26 Apr 2016 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
HAMI411	P1	01:46:01 15 Apr 2016	01:47:27 15 Apr 2016	01:49:57 15 Apr 2016	05:57:23 15 Apr 2016
HAMI412	P2	01:46:01 15 Apr 2016	01:48:17 15 Apr 2016	01:50:34 15 Apr 2016	05:01:59 15 Apr 2016
PUKE431	P1	01:53:53 15 Apr 2016	01:55:58 15 Apr 2016	02:03:36 15 Apr 2016	03:44:29 15 Apr 2016
CHAR427	PR	01:53:47 15 Apr 2016	01:54:18 15 Apr 2016	02:07:46 15 Apr 2016	04:14:35 15 Apr 2016
CHAR4219	LU	02:06:14 15 Apr 2016	02:08:57 15 Apr 2016	02:11:57 15 Apr 2016	04:18:09 15 Apr 2016
WAIKATO3	OF	02:00:29 15 Apr 2016	02:00:29 15 Apr 2016	02:16:53 15 Apr 2016	02:18:09 15 Apr 2016
NGAR3326	CV	02:32:08 15 Apr 2016	02:33:12 15 Apr 2016	02:53:18 15 Apr 2016	04:42:32 15 Apr 2016
FIWAIKATO1	FSO				05:40:06 15 Apr 2016
HAMI4118	CUHU	01:53:50 15 Apr 2016			03:19:50 15 Apr 2016
CHAR4217	ST	01:53:46 15 Apr 2016			02:15:58 15 Apr 2016

Start->Alert 7 min 10 min



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
HAMI411	00:00:44	00:03:56	00:04:40	04:12:06
HAMI412	00:00:44	00:04:33	00:05:17	03:16:42
PUKE431	00:08:36	00:09:43	00:18:19	01:59:12
CHAR427	00:08:30	00:13:59	00:22:29	02:29:18
CHAR4219	00:20:57	00:05:43	00:26:40	02:32:52
WAIKATO3	00:15:12	00:16:24	00:31:36	00:32:52
NGAR3326	00:46:51	00:21:10	01:08:01	02:57:15
FIWAIKATO1				03:54:49
HAMI4118	00:08:33			01:34:33
CHAR4217	00:08:29			00:30:41

Notifications

Date	Time	Party Notified
15 Apr 2016	01:49:20	WEL
15 Apr 2016	01:50:27	WEL NETWORKS
15 Apr 2016	01:51:52	BLUE WATCH CALLBACKS PER PAGER
15 Apr 2016	01:51:59	AREA WAIKATO RE K99
15 Apr 2016	01:52:01	E TEXT HAMILTON BLUE DONE 01:52
15 Apr 2016	01:53:06	ETA FOR WEL NETWORKS 15-20 MINS
15 Apr 2016	01:57:28	BLUE AND BROWN CALLBACKS DUE TO 2ND ALARM
15 Apr 2016	01:57:34	HAMILTON BLUE/BROWN E TEXT DONE 01:57
15 Apr 2016	01:58:47	AREA WAIKATO RE 2ND ALARM
15 Apr 2016	02:12:38	PAGING HAMILTON BLUE/BROWN DONE 02:12
15 Apr 2016	02:14:48	5 YES'S TO E TEXT 02:14
15 Apr 2016	02:22:20	ADVISED HAMI FIRE WHEN THEY GET 4 CREW TO TAKE 415 TO WOODWARD INSTEAD OF
15 Apr 2016	02:24:12	FULL BRIGADE CALLOUT PAGED
15 Apr 2016	02:24:22	4 WATCHES DONE E TEXT AS OF 02:24
15 Apr 2016	02:32:31	3326 ADV THEY R READY TO ROLL
15 Apr 2016	02:38:17	AAC ████████ ACK PAGE
15 Apr 2016	02:41:40	FIRECOM OPS MANAGER ACK PAGE AND SITREP PASSED
15 Apr 2016	02:54:45	HAMILTON FIRE ADV THEY HAVE A CREW FOR 413 AND 337 @ HAMILTON ON COVER MOVE

15 Apr 2016	02:54:59	FIWAIKATO1 PUT THRU TO HAMI411
-------------	----------	--------------------------------

Message Log

Time	Message
01:45:42	INC INFO: HOUSE FIRE
01:45:44	** LOI search completed at 15/04/16 01:45:44
01:45:52	** Recommended unit HAMI411 for requirement PUMP (>1.0 km)
01:45:52	** Recommended unit HAMI412 for requirement PUMP (>1.1 km)
01:46:06	8 UNITS IN TOTAL - UPSTAIRS ON FIRE
01:46:42	DOWN A LONG DRIVEWAY - LOTS OF UNITS
01:47:28	Unit HAMI411 [K1 : PROCEEDING TO INCIDENT]
01:48:18	Unit HAMI412 [K1 : PROCEEDING TO INCIDENT]
01:48:42	Unit HAMI411 [COMCEN COM : MESSAGE] MULTIPLE CALLS TO THIS EVENT AND IT IS DOWN
01:48:42	A LONG DRIVEWAY
01:49:22	COVERING UNIT CHAR427 DISPATCHED TO STATION HAMILTON
01:49:22	D0710064
01:49:24	CALLER SAID FLAT WELL ABLASE ON THIRD FLOOR WINDOWS HAVE BLOWN OUT
01:49:58	Unit HAMI411 [K99 : PROPERTY FIRE WELL INV]
01:50:11	Unit HAMI412 [KC : UNIT CALLING]
01:50:35	Unit HAMI412 [K2 : IN ATTENDANCE AT INCIDENT]
01:50:37	Unit HAMI412 [SITREP :] ACTIVATE BLUE WATCH CALL BACK PAGERS
01:50:42	INC INFO: HOUSE FIRE TOC 01:45 TOA 01:49
01:52:57	Unit HAMI411 [KP : PRIORITY MESSAGE]
01:53:18	Unit HAMI411 [KP : PRIORITY MESSAGE] TRANSMIT SECOND ALARM
01:53:27	FIR2AMB HOUSE FIRE 2ND ALARM TXTD
01:53:35	FIR2POL HOUSE FIRE 2ND ALARM TXTD
01:53:37	** Alarm level updated to 2
01:53:37	** Recommended unit HAMI4118 for requirement COMU (>1.1 km)
01:53:37	** Recommended unit CHAR427 for requirement PUMP (>4.5 km)
01:53:37	** Recommended unit PUKE431 for requirement PUMP (>6.7 km)
01:53:37	** Recommended unit CHAR4217 for requirement SALV (>4.6 km)
01:53:49	AMBO EVENT 0077-1-2016/04/15-FIR LINKED AT 15/04/2016 01:53:49
01:54:19	Unit CHAR427 [K1 : PROCEEDING TO INCIDENT]
01:55:59	Unit PUKE431 [K1 : PROCEEDING TO INCIDENT]
01:56:12	Unit HAMI411 [KC : UNIT CALLING]
01:57:59	Unit HAMI411 [SITREP :] SO [REDACTED] 1 APRATMENT ON SECOND STORY BLOCK OF 8 WELL
01:57:59	INV IN FIRE BRIG AT WORK WITH 1 LPD OFFENSIVE INTERIEOR FIRE ATTACK
01:58:18	Unit HAMI411 [COMCEN COM : MESSAGE] ADV THAT POWER IS 15 MINS OUT

02:00:30 Unit WAIKATO3 [K1 : PROCEEDING TO INCIDENT]
02:02:08 ** Requirement PUMP added for alarm level 2
02:03:37 Unit PUKE431 [K2 : IN ATTENDANCE AT INCIDENT]
02:07:46 Unit CHAR427 [K2 : IN ATTENDANCE AT INCIDENT]
02:08:57 Unit CHAR4219 [K1 : PROCEEDING TO INCIDENT]
02:10:21 COVERING UNIT NGAR337 DISPATCHED TO STATION HAMILTON
02:10:21 D0710064
02:11:58 Unit CHAR4219 [K2 : IN ATTENDANCE AT INCIDENT]
02:14:58 Unit CHAR4217 [KC : UNIT CALLING]
02:15:48 Unit CHAR4217 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
WOODWARD ST
02:15:48 JOB
02:16:54 Unit WAIKATO3 [K2 : IN ATTENDANCE AT INCIDENT]
02:17:42 Unit WAIKATO3 [SITREP :] WILL HEAD OFF TO WOODWARD ST
02:18:10 Unit WAIKATO3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:22:04 Unit HAMI411 [KC : UNIT CALLING]
02:22:20 TAKING 4118 TO WELLINGTON ST
02:24:08 Unit HAMI411 [SITREP :] FULL BRIG TURNOUT - DO YOU REQ THE CANTINE FROM
02:24:08 NGARUAWHAIA? - STAND BY
02:24:16 Unit HAMI411 [KC : UNIT CALLING]
02:25:03 Unit HAMI411 [SITREP :] SEND CANTEEN IF AVAILABLE
02:26:32 Unit HAMI411 [COMCEN COM : MESSAGE] BE ADV THAT WE HAVE A FURTHER CALL IN
02:26:32 WOODWARD THE FIRST RESPONDING UNITS WILL BE TAKING THE THE OSU SO
THERE WILL BE
02:26:32 A DELAYED T
02:29:38 Unit HAMI411 [SITREP :] NO CU NEEDED AND NO CANTEEN NEEDED
02:33:10 ** Cross Referenced to Event # F2058805 at: 15/04/16 02:33:10
02:33:13 Unit NGAR3326 [K1 : PROCEEDING TO INCIDENT]
02:33:14 Unit NGAR3326 [K1 : PROCEEDING TO INCIDENT]
02:40:05 HAMI FIRE ADVISE 4118 NO LONGER REQUIRED AND WILL CALL WHEN THEY HAVE A
FULL
02:40:05 CREW ON STATION
02:47:11 Unit HAMI411 [KC : UNIT CALLING]
02:47:44 Unit HAMI411 [K11F : FIRE SAFETY REQUIRED]
02:47:46 Unit NGAR3326 [KC : UNIT CALLING]
02:48:53 Unit NGAR3326 [SITREP :] WE ARE ENROUTE TO WELLINGTON ST IS THAT STILL THE
02:48:53 LOCATION YOU WANT US TO GO TO? - AFFIRM
02:53:19 Unit NGAR3326 [K2 : IN ATTENDANCE AT INCIDENT]
02:54:30 Unit HAMI411 [COMCEN COM : MESSAGE] STANDBY FOR PHONE CALL
03:19:52 Unit HAMI4118 [K7 : AT NORMAL STATION]
03:22:54 Unit PUKE431 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]

03:39:19	Unit HAMI411 [KC : UNIT CALLING]
03:39:56	Unit HAMI411 [SITREP :] BRIG DAMPENING DOWN HOTSPOTS AND UNDERTAKING SALVAGE
03:44:30	Unit PUKE431 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
04:14:37	Unit CHAR427 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
04:18:11	Unit CHAR4219 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:42:34	Unit NGAR3326 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
05:01:11	FIR2POL ** BRIGADE WOULD LIKE UNIT TO ATTEND AS 1 APARTMENT IS UNABLE TO BE
05:01:11	SECURED
05:02:01	Unit HAMI412 [K7 : AT NORMAL STATION]
05:28:50	Unit HAMI411 [KC : UNIT CALLING]
05:29:16	Unit HAMI411 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
05:40:07	Unit FIWAIKATO1 [K6 : ON TELEPAGER]
05:47:35	6
05:57:25	Unit HAMI411 [K7 : AT NORMAL STATION]
07:54:43	UNIT WAIKATO3 ALERT TIME [NULL] ADJUSTED TO
07:54:43	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
07:54:43	Qualifier 2:

Incident

CAD Number F2058799
Incident Reporter [REDACTED]
Incident Controller [REDACTED]
Distance Travelled (km) 2
Delay In Receiving Call

Property Details

Occupant No name recorded
Building Owner Rented property
General Property Use Flat, Apartment, Home unit
Special Property Use Flats, Apartments, Units 3 to 10
Purpose Group

Actions

Persons Reported No
Trapped
Evacuation Status Evacuation in progress
Action Prior 1
Action Prior 2

Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location Bedroom, Sleeping area, Cell: under 5 persons
Level 1st floor

Equipment Used

Quantity	Equipment
1	
16	
2	Hose reel, high pressure delivery
1	Low pressure delivery
8	
2	
1	

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Totally involved fire
Heat Source Cigarette, Cigar or Smoking materials
Termination Stage Flame
First Object Ignited Bedding eg. Blankets, Sheets, Duvet
First Object Material Fabric, Fibre (finished)
Second Object Ignited Bedding eg. Mattress, Pillow
Second Object Material Fabric, Fibre (finished)
Indicated Cause Falling asleep smoking
Certainty of Cause High
Age of Person Persons: 19 - 64 yrs

Ethnicity [REDACTED]
 Gender [REDACTED]
 FAIP Service Offered Unknown

Structure

Area of One Floor		400
Age of Building	1970 - 1991	
Structural Frame Type	Reinforced concrete with non-combustible cladding	
Number of Floors		2
Number of Basements		0
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)	
Material Generating Most Flame	Multiple forms ignited	
Material Generating Most Smoke	Multiple forms ignited	
Avenue of Flame Travel	Furniture, fixtures	
Avenue of Smoke Travel	Furniture, fixtures	
Extent of Flame Damage	Confined to fire cell of origin	
Area of Flame Damage		60
Extent of Smoke Damage	Confined to floor of origin	
Area of Smoke Damage		120
Extent of Water Damage	Confined to structure of origin	
Area of Water Damage		150
Extent of Fire Control Damage	Confined to structure of origin	
Area of Fire Control Damage		100

Comments

4/15/2016 11:27:14 AM

Reporter Comments

FSO Requested at incident F2058799 on 15 Apr 2016 01:45

4/26/2016 4:54:54 PM

Reporter Comments

The incident was caused by carelessness with a cigarette in bed. I was able to reach this conclusion due to the occupant in the apartment saying that is what happened.