
SMS Incident Report

12/03/2018 11:25:10

Summary		
CAD Number	F2481109	Status Closed
Station	Takapuna Station	
Incident Started	14/02/2018 07:02:38	Incident Ended 14/02/2018 10:29:10
Incident Type	1101: Structure fire with damage	
Common Name	BERKELEY CINEMAS TAKAPUNA	
Address	/ 32 Anzac Street Takapuna	
Alarm Method	111 Telephone	Alarm Level 2
PFA Number		
Zone	148069	
Map Grid E	1758109	Map Grid N 5927348
First Caller		First Caller Contact
Incident Closed	14/02/2018 10:36:13	(C)
Report Completed	8:25, Mon 26 Feb 2018 by Shaun Pilgrim	
Responses		

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
TAKA807	PR	07:03:30 14 Feb 2018	07:04:34 14 Feb 2018	07:08:59 14 Feb 2018	10:31:57 14 Feb 2018
DEVO811	P1	07:03:33 14 Feb 2018	07:05:04 14 Feb 2018	07:11:07 14 Feb 2018	09:31:50 14 Feb 2018
WAITEMATA3	OF	07:15:36 14 Feb 2018	07:18:18 14 Feb 2018	07:22:05 14 Feb 2018	07:48:42 14 Feb 2018
BIRK821	P1	07:13:21 14 Feb 2018	07:14:46 14 Feb 2018	07:23:38 14 Feb 2018	09:27:56 14 Feb 2018
AUCK2018	СИНИ	07:13:15 14 Feb 2018	07:14:50 14 Feb 2018	07:26:16 14 Feb 2018	08:21:04 14 Feb 2018
ALBA851	P1	07:13:18 14 Feb 2018	07:15:51 14 Feb 2018	07:27:21 14 Feb 2018	09:26:14 14 Feb 2018
PARN255	HPNP	07:14:59 14 Feb 2018	07:16:08 14 Feb 2018	07:29:43 14 Feb 2018	08:44:48 14 Feb 2018
AUCKOSU1	SV	07:19:15 14 Feb 2018	07:19:21 14 Feb 2018	07:42:40 14 Feb 2018	07:58:41 14 Feb 2018
FIWAITEM3	FSO	07:41:12 14 Feb 2018	07:45:03 14 Feb 2018	08:06:24 14 Feb 2018	10:32:40 14 Feb 2018
AUCK206	HPNP	07:11:56 14 Feb 2018			07:15:46 14 Feb 2018



Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
TAKA807	00:00:52	00:05:29	00:06:21	03:29:19
DEVO811	00:00:55	00:07:34	00:08:29	02:29:12
WAITEMATA3	00:12:58	00:06:29	00:19:27	00:46:04
BIRK821	00:10:43	00:10:17	00:21:00	02:25:18
AUCK2018	00:10:37	00:13:01	00:23:38	01:18:26
ALBA851	00:10:40	00:14:03	00:24:43	02:23:36
PARN255	00:12:21	00:14:44	00:27:05	01:42:10
AUCKOSU1	00:16:37	00:23:25	00:40:02	00:56:03
FIWAITEM3	00:38:34	00:25:12	01:03:46	03:30:02
AUCK206	00:09:18		J.	00:13:08
				•
Notifications			×0`	
D = t =	la (

Elapsed Times

Notifications

Date	Time	Party Notified
14 Feb 2018	07:13:03	OSU AUCKLAND PER PAGER RE 2ND ALASRM
14 Feb 2018	07:13:41	DID NOT ATTACH PARN255 AS PER RECOMMEND AS AUCK206 ALREADY ATTACHED
14 Feb 2018	07:14:04	AMB VIA INTERCAD (FYI)
14 Feb 2018	07:14:06	AAC WAITEMATA PER PAGER - 2ND ALARM TRANMSITTED
14 Feb 2018	07:14:09	POL VIA INTERCAD (FYI)
14 Feb 2018	07:14:12	VECTOR : HOLDING
14 Feb 2018	07:14:16	AAC MONRAD / AAC BOOTH PER PAGER
14 Feb 2018	07:15:54	AAC MACKERETH ACK PAGER - RESPONDING
14 Feb 2018	07:15:59	VECTOR : NO ETA AT THIS TIME
14 Feb 2018	07:16:52	AAC BOOTH ACK PAGER
14 Feb 2018	07:20:05	AC ODONOGHUE ACK PAGER
14 Feb 2018	07:22:31	ICU.AUCKLAND WITH GREATER ALARM ATTENDANCE VIA E-MAIL
14 Feb 2018	07:22:44	CORRECTION TO ABOVE, FROM WAITEMATA3 - SHOULD READ SITREP RATHER THAN STOP
14 Feb 2018	07:22:44	ETA 30-40 MINS AS @ 0722 HRS DUE TO BUMPER TO BUMPER TRAFFIC (CURRENTLY IN
14 Feb 2018	07:23:42	CORRECTION : ETA VECTOR 30-40 MINS (PER ABOVE)
14 Feb 2018	07:25:09	AAC MONRAD ACK PAGER
14 Feb 2018	07:26:53	PFA 115967 , 115968, ADT - WILL CALL BACK WITH ETA

Message Log

Time	Message
07:03:16	INC INFO: SMOKE COMING FROM SIGN - OUTSIDE OF BUILDING
07:03:17	** LOI search completed at 14/02/18 07:03:17

SMS Incident Report F	2481109
-----------------------	---------

3/7

07:03:22	** Recommended unit TAKA807 for requirement PUMP (>2.7 km)
07:03:22	** Recommended unit DEVO811 for requirement PUMP (>4.5 km)
07:04:02	SMOKE IS COMING FROM BERKELEY CINEMA SIGN ON OUTSIDE OF BUILDING
07:04:34	Unit TAKA807 [K1 : PROCEEDING TO INCIDENT]
07:05:05	Unit DEVO811 [K1 : PROCEEDING TO INCIDENT]
07:06:01	Unit TAKA807 [KC : UNIT CALLING]
07:06:14	Unit TAKA807 [SITREP :] DO YOU HAVE ANY FURTHER INFORMATION?
07:06:29	Unit TAKA807 [COMCEN COM : MESSAGE] THE CALLER SAID ITS THE BERKELEY CINEMAS
07:06:29	SIGN
07:09:00	Unit TAKA807 [K77 : NOTHING SHOWING]
07:10:33	Unit TAKA807 [KC : UNIT CALLING]
07:11:08	Unit DEVO811 [K2 : IN ATTENDANCE AT INCIDENT]
07:11:13	Unit TAKA807 [SITREP :] SSO PILGRIM - FIRE IN WALL CAVITY ABOVE SIGN - MAKE
07:11:13	AERIALS ONE - HYDROLIC ELEVATING PLATFORM
07:11:31	Unit TAKA807 [SITREP :] WE HAVE JUST HAD A MANUAL SYSTEM ACTIVATION FROM THE
07:11:31	SAME BUILDING
07:11:48	** Requirement AERIAL added for alarm level 1
07:11:51	** Recommended unit AUCK206 for requirement ADHOC AERIAL (>7.8 km)
07:12:09	Unit TAKA807 [KP : PRIORITY MESSAGE]
07:12:23	Unit TAKA807 [SITREP :] TRANSMIT 2ND ALARM
07:12:23	Unit TAKA807 [KP : PRIORITY MESSAGE]
07:13:00	Unit AUCK206 [KC : UNIT CALLING]
07:13:07	** Alarm level updated to 2
07:13:07	** Recommended unit PARN255 for requirement AERIAL (>7.0 km)
07:13:07	** Recommended unit AUCK2018 for requirement COMU (>7.8 km)
07:13:07	** Recommended unit ALBA851 for requirement PUMP (>7.2 km)
07:13:07	** Recommended unit BIRK821 for requirement PUMP (>5.7 km)
07:13:13	
07:13:29	FIR2POL : NOTIFICATION ONLY 2ND ALARM BLDG FIRE (FYI)
07:13:36	FIR2AMB : NOTIFICATION ONLY 2ND ALARM BLDG FIRE (FYI)
07:13:58	AMBO EVENT 0147-1-2018/02/14-FIR LINKED AT 14/02/2018 07:13:58
07:14:43	Unit AUCK206 [SITREP :] THE AUCK206 IS A LADDER YOU WILL NEED TO SEND PARN255
07:14:47	Unit BIRK821 [K1 : PROCEEDING TO INCIDENT]
07:14:51	Unit AUCK2018 [K1 : PROCEEDING TO INCIDENT]
07:15:47	Unit AUCK206 [K7 : AT NORMAL STATION]
07:15:50	Unit AUCK206 [K28 : UNIT IS TO RETURN TO STATION]
07:15:52	Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]
07:16:09	Unit PARN255 [K1 : PROCEEDING TO INCIDENT]
07:16:20	COVERING UNIT GREY261 DISPATCHED TO STATION TAKAPUNA
07:16:20	TERMINAL: D0710063

SMS Incident Report	F2481109	4/7	12/03/2018 11:25:10
07:17:12	COVERING UNIT WI	EST671 DISPATCHED TO STATION ALBANY AT	
07:17:12	TERMINAL: D07100	63	
07:17:27	End of Duplicate Eve	ent data	
07:17:27	** Cross Referenced	to Event # F2481114 at: 14/02/18 07:17:27	
07:17:27	AL: 115968 07:11:04	INITIAL - AL	
07:17:27	Duplicate Event:Loca	ation = 32 ANZAC ST AUCKLAND #115968Cross Str	eet 1CAMPBELL
07:17:27	RDCross Street 2LA	KE RD, Type = SPRNKLR, Subtype = default, Call So	ource =
07:17:27	PANEL: FRONT OF	BUILDING	- G
07:17:27	** LOI search comple	eted at 14/02/18 07:11:07	
07:17:27	PFAAlarm Level1		<i>`</i> ``
07:17:27	NO ACCESS NUMB	ER	O
07:18:19	Unit WAITEMATA3 [K1 : PROCEEDING TO INCIDENT]	
07:19:16	Unit AUCKOSU1 [K3	38 : ASSOCIATE THIS UNIT TO EVENT - EVENT AI	DDRESS]
07:19:21	Unit AUCKOSU1 [K	1 : PROCEEDING TO INCIDENT]	
07:19:56	Unit TAKA807 [KC :	UNIT CALLING]	
07:20:53	Unit TAKA807 [SITR	REP :] ONE THREE LEVEL BUILDING 30M X 30M -	USED AS
07:20:53	ENTERTAINMENT C EXTERIOR	COMPLEX - FIRE BEHIND EXTERIOR SIGN INTO W	VALL - OFFENSIVE
07:20:53	CUT OFF - INTERNA	AL SEARCH BEING CONDUCTED - ONE HIGH AND	D MEDIUM LADDER IN USE
07:21:01	Unit WAITEMATA3 [STOP : MESSAGE] COPIED	
07:22:06	Unit WAITEMATA3 [K2 : IN ATTENDANCE AT INCIDENT]	
07:22:37	Unit TAKA807 [KC :	UNIT CALLING]	
07:22:44	NORTHCOTE AREA		
07:23:03	Unit TAKA807 [SITR	REP :] CAN YOU PLEASE RESPOND BUILDING RE	EP OF KEYHOLDER TO
07:23:03	THE PREMISE		
07:23:38	Unit BIRK821 [K2 : I	IN ATTENDANCE AT INCIDENT]	
07:25:11	* NFS1 ADVISED		
07:26:16	Unit AUCK2018 [K2	: IN ATTENDANCE AT INCIDENT]	
07:27:22	Unit ALBA851 [K2 : I	IN ATTENDANCE AT INCIDENT]	
07:29:44	Unit PARN255 [K2 :	IN ATTENDANCE AT INCIDENT]	
07:34:40	Unit TAKA807 [SITR	REP :] (BY PHONE) ARE YOU ABLE TO LOOK UP T	TO SEE IF THERE"S A
07:34:40	KEY BOX/ACCESS	NUMBER	
07:34:51	Unit TAKA807 [COM	CEN COM : MESSAGE] (BY PHONE) THERE''S NO	THING SHOWING
07:40:08	Unit TAKA807 [KC :	UNIT CALLING]	
07:40:22	Unit TAKA807 [K11F	F : FIRE SAFETY REQUIRED]	
07:40:40	INC INFO: FIRE IN V	NALL CAVITY TOC 07:03 TOA 07:08	
07:42:41	Unit AUCKOSU1 [K2	2 : IN ATTENDANCE AT INCIDENT]	
07:45:04	Unit FIWAITEM3 [K1	1 : PROCEEDING TO INCIDENT]	
07:48:43	Unit WAITEMATA3 [K6 : ON TELEPAGER]	
07:58:42	Unit AUCKOSU1 [K4	4 : ON RT INSIDE NORMAL TURNOUT AREA]	

SMS Incident Report	F2481109	5/7	12/03/2018 11:25:10
08:06:25	Unit FIWAITEM3 [K	2 : IN ATTENDANCE AT INCIDENT]	
08:21:06	Unit AUCK2018 [K4	: ON RT INSIDE NORMAL TURNOUT AREA]	
08:32:15	POL2FIR: CONFIRM	IING WE ARE NOT REQ FOR ATTENDANCE?	
08:33:58	FIR2POL: AFFIRM, I	NOTIFICATION ONLY	
08:42:29	тнх		
08:42:33	** Event Type chang	ed from 1F(2) to 1F(4) at: 14/02/18 08:42:33	
08:44:50	Unit PARN255 [K3 :	ON RT OUTSIDE NORMAL TURNOUT AREA]	*
09:12:04	** Cancel Event:Even	nt Canceled by InterCAD	C C
09:12:04	EXTERNAL EVENT	CLOSED BY EXTERNAL AGENCY	
09:12:04	Incident Closed. Rea	son: 030 COMMS Referred to Fire	<i>`</i> ``
09:26:15	Unit ALBA851 [K3 :	ON RT OUTSIDE NORMAL TURNOUT AREA]	
09:27:56	Unit BIRK821 [K3 : 0	ON RT OUTSIDE NORMAL TURNOUT AREA]	
09:31:51	Unit DEVO811 [K4 :	ON RT INSIDE NORMAL TURNOUT AREA]	0
10:28:12	Unit TAKA807 [KC :	UNIT CALLING]	
10:29:10	Unit TAKA807 [K47	: STOP MESSAGE: MESSAGE UNCHANGED FR	OM INFORMATIVE] GREY261
10:29:10	NO LONGER REQU	IRED TO STANDBY AT TAKAPUNA	
10:31:39	Unit TAKA807 [KC :	UNIT CALLING]	
10:31:58	Unit TAKA807 [K10		
10:32:41	Unit FIWAITEM3 [K	6 : ON TELEPAGER]	
10:36:12	** Assigned Result C	code: STRU, Detailed Event Type: 1100, Qualifier 1	: Q1,
10:36:12	Qualifier 2:	0	

Incluent	XX
CAD Number	F2481109
Incident Reporter	Shaun Pilgrim
Incident Controller	
Distance Travelled (km)	
Delay In Receiving Call	
Property Details	S
Occupant	O Berkley Cinemas
Building Owner	Owner occupied
General Property Use	Recreational use, Theatre, Indoor sports, Pool, Park, Zoo, Aquarium
Special Property Use	Cinema, Picture theatre
Purpose Group	
Actions	
Actions Persons Reported Trapped	t

Evacuation Status

Not occupied at time of incident

Action Prior 1

Action Prior 2

Action Taken

Extinguishment and ventilation

Civilians

Civilians Rescue	1		0
Civilians Extricate	ed	× .	0
Civilians Assisted	ł	~ G~	1
Civilians Evacuat	ed		0
Origin			
Location	Vacant structural area		
Level	1st floor		
Equipment Used	k		

6/7

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery
1	Aerial Ladder/Platform
1	Positive Pressure Ventilation Fan (PPV)

Equipment Involved

Equipment Involved		
Year		2000
Make		
Model	$\mathbf{x}_{\mathbf{x}}$	
Fire		
Arrival Condition	Small fire	
Heat Source	Short circuit arc: Unspecified	
Termination Stage		
First Object Ignited		
First Object Material		
Second Object Ignited		
Second Object Material		
Indicated Cause	Equipment overloaded	
Certainty of Cause	High	
Age of Person		
Ethnicity		
Gender		

12/03/2018 11:25:10

FAIP Service Offered	No	FAIP Service Accepted	No
Alarms			
Type of Alarm Initiating Call	Smoke Detector Syster	m (Monitored)	
Performance of System	Detector in room of orig	jin - not classified above	
Failure/Ineffectiveness of system			N
lumber of sprinkler heads perated			NG1
Comments			
		2/26/2018 8:25:12 AM	porter Comments
		the	
2	sedunder		
Pelo			