SMS Incident Report

24/07/2017 13:54:07

Summary

CAD Number F2346830 Status Closed

Station Auckland City Station

Incident Started 20/07/2017 11:08:02 Incident Ended 20/07/2017 11:23:55

Incident Type 7104: False alarm: Accidental operation

Common Name EAST ON QUAY

Address 32 MAHUHU CRESCENT AUCKLAND CENTRAL

Alarm Method Manual PFA Call Alarm Level 1

PFA Number 116711 **Zone** 142505

 Map Grid E
 1758314
 Map Grid N
 5920683


First Caller Contact

Incident Closed 20/07/2017 11:46:50

Report Completed 18:20, Thur 20 Jul 2017 by Phil Grace

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
AUCK207	PR	11:08:20 20 Jul 2017	11:09:51 20 Jul 2017	11:14:26 20 Jul 2017	11:24:02 20 Jul 2017
REMU211	P1	11:08:23 20 Jul 2017	11:09:55 20 Jul 2017	11:16:57 20 Jul 2017	11:20:15 20 Jul 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
AUCK207	00:00:18	00:06:06	00:06:24	00:16:00
REMU211	00:00:21	00:08:34	00:08:55	00:12:13

Message Log

Time	Message	
11:08:02	AL: 116711 11:08:02 INITIAL - AL	
11:08:02	PANEL: SPRINKLER VALVE ROOM	
11:08:03	** LOI search completed at 20/07/17 11:08:03	
11:08:13	** Recommended unit AUCK207 for requirement PUMP (>1.8 km)	
11:08:13	** Recommended unit REMU211 for requirement PUMP (>3.5 km)	
11:08:20	ACCESS NO:	
11:09:52	Unit AUCK207 [K1 : PROCEEDING TO INCIDENT]	
11:09:56	Unit REMU211 [K1 : PROCEEDING TO INCIDENT]	
11:10:38	INC INFO: FIRE ALARM SOUNDING	
11:10:38	Duplicate Event:Location = 32-34 MAHUHU CR,AUCKLAND CENTRAL,AUCKLAND, Type =	
11:10:38	STRU - STRUCTURE FIRE, Caller Name = PREPAID/TELECOM, Caller Ph Number =	
11:10:38	, Caller Address = TELECOM CELLULAR 027, UNKNOWN, UNKNOWN, Call	
11:10:38	Source = 111Inc InfoFIRE ALARM SOUNDING, Event Source = Fire 111	
11:10:38	End of Duplicate Event data	
11:14:27	Unit AUCK207 [K77 : NOTHING SHOWING]	
11:16:06	Unit AUCK207 [KC : UNIT CALLING]	
11:16:30	Unit AUCK207 [SITREP :] SSO GRACE IPS THIRD FLOOR RIGHT	
11:16:45	Unit AUCK207 [KC : UNIT CALLING]	
11:16:58	Unit REMU211 [K2 : IN ATTENDANCE AT INCIDENT]	
11:17:02	Unit REMU211 [K2 : IN ATTENDANCE AT INCIDENT]	
11:17:04	Unit AUCK207 [K28-1 : RETURN OTHER RESPONDING UNITS]	
11:20:16	Unit REMU211 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
11:23:26	Unit AUCK207 [KC : UNIT CALLING]	
11:23:55	Unit AUCK207 [K46-2 : STOP MESSAGE: FALSE ALARM ACCIDENTAL] BUIDING RENOVATIONS	
11:24:03	Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
11:46:49	** Assigned Result Code: SPRNKLR, Detailed Event Type: 7100, Qualifier 1: Q1,	
11:46:49	Qualifier 2:	

Incident

CAD Number	F2346830
Incident Reporter	Phil Grace
Incident Controller	SSO Phil Grace
Distance Travelled (km)	
Delay In Receiving Call	

False Alarm

Detector Type	Manual call point
False Alarm Cause	Human Intervention Accidential alarm activation by (b) contractor (not the service agent)

Other Cause

Property Details

Occupant

Building Owner

General Property Use Office, Bank, Embassy, Fire/Ambulance/Police station

Special Property Use Office: General business

Purpose Group WL - Working, Business or Storage Light Fire Hazard

Comments

7/20/2017 6:20:16 PM

Reporter Comments

zeleased under the MCP - Level 3 Right - Renovations, pulled wire

Phil Grace